



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - DIFFUSER CASE ASSEMBLY - TO ANNOUNCE THE AVAILABILITY OF
A SPARE FUEL NOZZLE CLASSIFIED SPACER TO PERMIT REPAIR OF THE FUEL NOZZLE AND
SUPPORT ASSEMBLY

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2527M-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

73-13-00

Compliance Category Code

NA

Internal Reference No.

98VC007A, 98VC007C

Sep.6/00

V2500-ENG-70-0796

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - DIFFUSER CASE ASSEMBLY - TO ANNOUNCE THE AVAILABILITY OF
A SPARE FUEL NOZZLE CLASSIFIED SPACER TO PERMIT REPAIR OF THE FUEL NOZZLE AND
SUPPORT ASSEMBLY

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A319, A320, A321

McDonnell Douglas MD-90

(2) Engine: V2500-A1 Engines
V2522-A5 Engines
V2524-A5 Engines
V2527-A5 Engines
V2527E-A5 Engines
V2527M-A5 Engines
V2530-A5 Engines
V2533-A5 Engines
V2525-D5 Engines
V2528-D5 Engines

B. Reason

To announce the availability of newly released repair parts.

C. Compliance

For information only.

D. Approval

The Part Number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) IAE Engineering Change 98VC007A, 98VC007C.

(2) V2500-A1 Engine Illustrated Parts Catalog (S-V2500-1IA) to add the new part.

(3) V2500-A5 Engine Illustrated Parts Catalog (S-V2500-2IA, S-V2500-2IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB), Chapter/Section 72-45-20, 72-45-25, 72-45-30) to add the new part.

(4) V2500-D5 Engine Illustrated Parts Catalog (S-V2500-3IA, S-V2500-3IB) to add the new part.

Printed in Great Britain

Sep.6/00

V2500-ENG-70-0796

Page 2



International Aero Engines INFORMATION BULLETIN

F. General Information

A New Repair Scheme is being introduced into the V2500 Engine Manual (E-V2500-1IA, and EV2500-3IA) which requires Classified Spacers for accomplishment.

<u>ATA Ref, No.</u>	<u>Repair Scheme</u>	<u>Title</u>
73-13-41	VRS 3589	Fuel Nozzle and Support Assembly - Spacer Replacement

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price(\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
------------------------------	-----	----------------------------	---------	------------------------------	-----------------------------

Applicability: For each V2500-A1, V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5, V2525-D5, V2528-D5 Engine to incorporate this Service Bulletin.

2A1045 (73-13-41)	1		.Spacer	(01-130)	(1)(A)
			OR		
2A1045CL1 (73-13-41)	1		.Spacer	(01-131)	(1)(A)
			OR		
2A1045CL2 (73-13-41)	1		.Spacer	(01-132)	(1)(A)
			OR		
2A1045CL3 (73-13-41)	1		.Spacer	(01-133)	(1)(A)
			OR		
2A1045CL4 (73-13-41)	1		.Spacer	(01-134)	(1)(A)
			OR		
2A1045CL5 (73-13-41)	1		.Spacer	(01-135)	(1)(A)
			OR		
2A1045CL6 (73-13-41)	1		.Spacer	(01-136)	(1)(A)

H. Instructions/Disposition Code Statements:

- (1) New Parts are for repair only of the Fuel Nozzle Support Assemblies.
- (A) The new part is currently available.

NOTE: The estimated unit prices, if shown, are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Sep.6/00

V2500-ENG-70-0796

Page 3