

PUBLICATION TRANSMITTAL RR-DERBY



International Aero Engines

400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA
TELEPHONE: 860 565 5515
FAX: 860 565 0600

P.O. BOX 31, DERBY
TELEGRAMS: 'ROYCAR' DERBY
TELEX: 37645
TELEPHONE: DERBY 242424

DATE: Oct 13/00

V2500-D5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin V2500-ENG-70-0799

Bulletin Initial Issue

Remove

Incorporate
Page 1 to 3 of the
Service Bulletin

Reason for change
Initial Issue

Printed in Great Britain

V2500-ENG-70-0799

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES


The effective pages to this Service Bulletin are as follows.

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
Bulletin		
1		Oct 13/00
2		Oct 13/00
3		Oct 13/00

Printed in Great Britain

V2500-ENG-70-0799

Transmittal - Page 2



International Aero Engines
INFORMATION BULLETIN

GENERAL INFORMATION BULLETIN - TO ANNOUNCE THE AVAILABILITY OF REPAIR PART FOR
THE BIFURCATION BOX ASSEMBLY

1. Planning Information

A. Effectivity

- (1) Aircraft
 - (a) Boeing-Douglas Product Division MD-90.
- (2) Engines
 - (a) V2525-D5, V2528-D5 Engines.

B. Reason

The purpose of this Service Bulletin is to provide the availability of a repair part for the bifurcation box assembly;

C. Compliance

For information only.

D. Approval

The part number changes and/or part modification are given in Section 2 and 3 of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

E. General Information

- (1) The material information portion of this bulletin provides the latest information concerning the availability of list name of articles involved.
- (2) A new Repair scheme will be introduced into the V2500 Engine Manual (E-V2500-3IA) which requires Repair part for its accomplishment.

<u>ATA Ref No.</u>	<u>Repair Scheme</u>	<u>Title</u>
72-38-27	VRS1915	Bifurcation Box Assembly - Replace the Support

F. References

- (1) Internal Reference 92VJ055-04
- (2) The Material Information section of this Service Bulletin provides the latest information concerning the availability of the support for the bifurcation box assembly.

Oct.13/00

V2500-ENG-70-0799

Page 1 of 3



International Aero Engines

INFORMATION BULLETIN

G. Other Publications Affected

- (1) Illustrated Parts Catalogue (IPC), Chapter/Section 72-38-27, Fig 01 will be revised to shown the part introduced by this Service Bulletin.
- (2) D5 Engine Manual (EM), Chapter/Section 72-38-27, will be revised to incorporate Repair VRS1915.

Oct.13/00

V2500-ENG-70-0799

Page 2



International Aero Engines
INFORMATION BULLETIN

2. Material Information

A. Material - Price and availability

The prices as shown are for estimated purposes only and as such are given in good faith without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current Price Catalog for current prices.

NEW PART NO. (ATA No.)	QTY	EST'D UNIT PRICE	KEYWORD	OLD PART No. (IPC No.)	INSTR DISP
5T0106 (72-38-27)	1	2,011.00	..Support	- (01-575)	(A)

B. Instruction Disposition Codes

(1) (A) New part will be available for future releases.

