

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE: 860 565 5515
FAX: 860 565 0600

DATE: Jan.22/02

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE - DERBY 242424

V2500-A1/A5 PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0806

Bulletin Initial Issue

Remove

Incorporate
Pages 1 to 3 of the
Service Bulletin

Reason for change
Initial issue

V2500-ENG-70-0806
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Jan.22/02
--	--	-----------

2		
---	--	--

		Jan.22/02
--	--	-----------

3		
---	--	--

		Jan.22/02
--	--	-----------

Printed in Great Britain



INFORMATION – AIR COOLING – IGNITION COOLING LEADS – INTRODUCTION OF ALTERNATIVE
TOROIDAL SEAL RINGS

1. Planning Information

A. Effectivity

- (1) Airbus A319
V2522-A5, V2524-A5, V2527M-A5 Engines
- (2) Airbus A320
 - (a) V2500-A1 Engines
 - (b) V2527-A5, V2527E-A5 Engines
- (3) Airbus A321
V2530-A5, V2533-A5 Engines
- (4) ATA Location
75-27-49

B. Reason

To announce the introduction of alternative ignition cooling lead toroidal seal rings

C. Compliance

For Information Only

D. Approval

The part number changes and/or part modifications described in sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA approved for the engine models listed.

E. References

- (1) IAE Engineering Change Number 01VR006

F. Other Publications Affected

- (1) Illustrated Parts Catalog (IPC), 1IA, 2IA, 2IB, 5IA, 5IB, 6IA, 6IB, 7IA, 7IB, 75-27-49 will be revised.



G. General Information

The Material Information section of this Service Bulletin provides the latest information concerning the availability of the affected parts.



2. Material Information

A. New production parts:

PART NO.	QTY	UNIT PRICE US DOLLARS
M83248-2-020	1	0.56
NAS1594-020	1	0.56

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For actual prices, refer to the IAE Price Catalogue or contact IAE's spare parts sales department.

B. Parts affected by this bulletin:

All Engines

75-27-49

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01095	M83248-2-020	1	Ring, sealing toroidal (V81349)	-	-	(A)
01095	NAS1594-020	1	Ring, sealing toroidal (V80205)	-	NAS1594-020	(A)
01495	M83248-2-020	1	Ring, sealing toroidal (V81349)	-	-	(B)
01495	NAS1594-020	1	Ring, sealing toroidal (V80205)	-	NAS1594-020	(B)

C. Instructions disposition codes:

(A) Alternatives.

(B) Alternatives.

3. Accomplishment Instructions

None.

