PUBLICATION TRANSMITTAL **RR-DERBY**



International Aero Engines

400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE: 860 565 5515 FAX: 860 565 0600

P.O.BOX 31, DERBY TELEGRAMS-'ROYCAR' DERBY TELEX-37645 **TELEPHONE-DERBY 242424**

DATE: Oct.22/01

V2500-A1 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin V2500-ENG-70-0807

Bulletin Initial Issue

Remove

Incorporate Page 1 to 3 of the Service Bulletin

Reason for change **Initial Issue**

V2500-ENG-70-0807

Transmittal - Page 1 of 2

5.7 CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED If any have not been received please advise publication Services, Rolls-Royce plc, Derby, England © Rolls-Royce plc (date as above) Printed in Great Britain

Printed in Great Britain



INFORMATION BULLETIN

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

Page	Revision Number	Revision Date
Bulletin		
Dulletili		Oct.22/01
2		Oct.22/01
-		
3		Oct.22/01

Printed in Great Britain

V2500-ENG-70-0807

Oct.22/01

Page 2



INFORMATION BULLETIN

GENERAL INFORMATION BULLETIN - TO ANNOUNCE THE NEW REPAIR ONLY PART FOR FAN CASE ASSEMBLY

1. Planning Information

A. Effectivity

- (1) Aircraft
 - (a) Airbus A320
- (2) Engines
 - (a) V2500-A1 Engines.

B. Reason

To announce the introduction of new repair only part for fan case assembly.

C. Compliance

Category Code 8

Accomplish based on the operators experience with the prior configuration.

D. Approval

The part number transactions are given in the "Material Information" section of this Service Bulletin. They obey the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

E. References

(1) Internal Reference 99VJ012B

F. General Information

- (1) The material information portion of this bulletin provides the latest information concerning the affected part.
- (2) The following existing Repair Scheme introduced into the V2500 Engine Manual (E-V2500-11A) will be revised to include the new part introduced by this Service Bulletin.

ATA Ref. No.	Repair Schemes	<u>Title</u>
72-32-85	VRS1958	Repair by replacement of the Acoustic Lining

V2500-ENG-70-0807

Apr.27/01



INFORMATION BULLETIN

(2) The following existing Repair Scheme introduced into the A320 Aircraft Maintenance Manual will be revised to include the new part introduced by this Service Bulletin.

ATA Ref. No.	Repair Schemes	Title
72-32-85	VRS1575	Repair by replacement of the Acoustic Lining

- (4) V2500 Engine Illustrated Parts Catalog (S-V2500-1IA), Chapter/Section 72-32-85 will be revised.
- (5) V2500 Power plant Illustrated Parts Catalog (PIP-V2500-1IA), Chapter/Section 72-32-85 will be revised.

Printed in Great Britain

V2500-ENG-70-0807

Page 2

Oct.22/01



INFORMATION BULLETIN

G. Material Information

NEW PART NO. (ATA No.)	QTY	EST'D UNIT PRICE	KEYWORD	OLD PART No. (IPC No.)	INSTR DISP
5R0292 (72-32-85)	4	1,100.00	.Lining, A/O acoustic - repair	5R0080 (01-950)	(A)(B) (1)
5R0292 (72-32-85)	1	1,100.00	.Lining, A/O acoustic - repair	5R0081 (01-955)	(A)(B) (1)
5R0292 (72-32-85)	1	1,100.00	.Lining, A/O acoustic - repair	5R0082 (01-960)	(A)(B) (1)

NOTE: The prices as shown are for estimated purposes only and as such are given in good faith without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current Price Catalog for current prices.

H. Instruction Disposition Codes

- (A) The old parts are no longer available.(B) The new parts are currently available.
- (1) Old and new parts are freely and fully interchangeable, both physically and functionally.

V2500-ENG-70-0807

Oct.22/01

