

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE: 860 565 5515
FAX: 860 565 0600

DATE: Oct. 3/01

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE - DERBY 242424

Printed in Great Britain

V2500-A1 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin EV2500-70-0811

Bulletin Initial Issue

Remove

Incorporate
Pages 1 to 4 of the
Service Bulletin

Reason for change
Initial Issue

V2500-ENG-70-0811

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED

If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England

© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Oct.3/01
--	--	----------

2		
---	--	--

		Oct.3/01
--	--	----------

3		
---	--	--

		Oct.3/01
--	--	----------

4		
---	--	--

		Oct.3/01
--	--	----------

Printed in Great Britain

V2500-ENG-70-0811
Transmittal - Page 2



INFORMATION – POWERPLANT – ANNOUNCEMENT OF REPAIR PARTS FOR FORWARD MOUNT SUPPORT

1. Planning Information

A. Effectivity

- (1) Airbus A320
 - (a) V2500-A1 Engines
- (2) ATA Location
 - 71-21-00

B. Concurrent Requirements

None.

C. Reason

- (1) Problem
 - Not applicable
- (2) Evidence
 - Not applicable
- (3) Substantiation
 - Not applicable
- (4) Objective
 - To announce the availability of repair parts for Forward Mount Support.
- (5) Effect of Bulletin on Workshop Procedures:
 - (a) Operation
 - Not affected
 - (b) Maintenance
 - Not affected
 - (c) Overhaul
 - Not affected

Oct. 3/01
Oct. 3/01

V2500-ENG-70-0811

Page 1 of 4



(d) Repair Schemes

Affected

(e) Interchangeability

Not affected

(f) Fits and Clearances

Not affected

D. Description

None

E. Compliance

Not applicable

F. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA approved for the engine models listed.

G. Manpower

Not applicable

H. Material Price and Availability

Modification kit is not required; parts are supplied as single line items.

For prices and availability of future spares see 2. Material Information.

I. Tooling Price and Availability

Not applicable

J. Industry Support Information

Not applicable

K. Weight and Balance

(1) Weight Change

Not applicable



(2) Moment Arm

Not applicable

(3) Datum

Not applicable

L. Electrical Load Data

Not applicable

M. Software Accomplishment Summary

Not applicable

N. References

(1) Internal Reference No.

IAE Engineering Change Number 91VJ005C-01

O. Other Publications Affected

(1) V2500-A1 Engine Illustrated Parts Catalog, Chapter/Section 71-21-11 will be revised to incorporate new part number.

(2) A new Repair Scheme is being introduced into the V2500 Engine Manual (E-V2500-1IA) which requires Repair Parts for its accomplishment.

VRS1105 - Forward mount support - Replace the damaged bush,
Chapter/Section 71-21-11

P. Interchangeability of Parts

Not applicable



2. Material Information

A. New production parts:

None.

B. Parts affected by this Bulletin:

V2500-A1 Engines

71-21-11

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
--------------------	--------------------	-----	------------	--------------------	---------------

The following Special Repair Parts are required to accomplish Repair Scheme VRS1105:

01-540	5A0994	2	Bush, pin thrust	-	(A)
01-740	5A0994	2	Bush, pin thrust	-	(A)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's spare parts sales department.

C. Instructions Disposition Codes:

(A) New part is currently available.

3. Accomplishment Instructions

None.