

400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600

DATE: Jul.25/06

P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

#### V2500-A1/A5/D5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits Revision 2 to Service Bulletin EV2500-70-0857 and Revision 2 to the Supplement

## **Document History**

Service Bulletin Revision Status

Initial Issue May 28/04

Revision 1 May 26/05

Supplement Revision Status

Initial Issue May 28/04

Revision 1 May 26/05

## **Bulletin Revision 2**

Remove
All pages of the
Summary
Summary
Summary
Summary
Summary
Summary
ST1946-280 for A1 engines
prior to Service Bulletin
V2500-ENG-72-0132 standard
and to make some minor
changes.

Pages 1 to 6 of the Pages 1 to 7 of the Service Bulletin Service Bulletin Strip46-280 for A1 engines prior to Service Bulletin V2500-ENG-72-0132 standard and to make some minor

changes.

V2500-ENG-70-0857
Transmittal - Page 1 of 3

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

All pages of Appendix 1 Pages 1 to 6 of Appendix 1

To add new part number ST1946-280 for A1 engines prior to Service Bulletin V2500-ENG-72-0132 standard and to make some minor changes.

## **Supplement Revision 2**

Remove All pages Incorporate Page 1

Reason for change To add new part number ST1946-280 for A1 engines prior to Service Bulletin V2500-ENG-72-0132 standard and to make some minor changes.

# LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 2 to the Bulletin and Revision 2 to the Supplement are as follows:

<u>Page</u>	Revision Number	<u>Revision Date</u>
Summary		
R 1	2	Jul.25/06
R 2	2	Jul.25/06
Bulletin		
R 1	2	Jul.25/06
R 2	2	Jul.25/06
R 3	2	Jul.25/06
R 4	2	Jul.25/06
R 5	2	Jul.25/06
R 6	2	Jul.25/06
R 7	2	Jul.25/06
Appendix 1		
R 1	2	Jul.25/06
R 2	2	Jul.25/06
R 3	2	Jul.25/06
R 4	2	Jul.25/06
R 5	2	Jul.25/06
R 6	2	Jul.25/06
Supplement		
R 1	2	Jul.25/06



R



#### **SERVICE BULLETIN**

#### INFORMATION - ENGINE - PROVIDE IMPROVED PREFORMED PACKINGS

# **SUMMARY**

#### PLANNING

#### A. EFFECTIVITY

Engine V2500-A1 Serial Numbers - Any engine as applicable.

Engine V2500-A5 Serial Numbers - Any engine as applicable.

Engine V2500-D5 Serial Numbers - Any engine as applicable.

#### **B. CONCURRENT REQUIREMENTS**

There are no concurrent requirements.

## C. REASON/PROBLEM

Problem:

The Pratt and Whitney supplier of certain packings has discontinued production. Therefore a new supplier is provided.

Background:

To provide a more readily available source of supply.

## D. DESCRIPTION

New improved packings are provided to replace certain discontinued packings.

#### E. COMPLIANCE

Category 7

Accomplish when supply of superseded parts has been depleted.

#### F. MANPOWER

(1)In Service

Not applicable

(2)At Overhaul

Not applicable

Total Necessary Man-hours - Not applicable

May 28/04 R Jul.25/06 SUMMARY V2500-ENG-70-0857



## 2. MATERIAL INFORMATION

Part Prices

R

A. The estimated price of new material to do this Service Bulletin using new replacement parts is \$275.10.

B. There is no kit provided to do this Service Bulletin.

**Printed in Great Britain** 



#### INFORMATION - ENGINE - PROVIDE IMPROVED PREFORMED PACKINGS

## 1. Planning Information

# A. Effectivity Data

(1) Airbus A319

Engine Models Applicable

V2522-A5, V2524-A5, V2527M-A5

Engine Serial Nos. - Any engine as applicable

(2) Airbus A320

Engine Models Applicable

V2500-A1

Engine Serial Nos. V0001 thru V0361

V2527-A5, V2527E-A5

Engine Serial Nos. - Any engine as applicable

(3) Airbus A321

Engine Models Applicable

V2530-A5, V2533-A5

Engine Serial Nos. - Any engine as applicable

(4) Boeing MD-90

Engine Models Applicable

V2525-D5, V2528-D5

Engine Serial Nos. V20001 thru V20285

## B. Concurrent Requirements

There are no concurrent requirements.

May 28/04 R Jul.25/06



# C. Reason

(1) Problem: The Pratt and Whitney supplier of certain packings has discontinued production. Therefore a new supplier is provided.

(2) Background: To provide a more readily availble source of supply.

(3) Substantiation: The new parts are presently being used successfully in all other Pratt and Whitney applications.

(4) Effects of Bulletin on:

Removal/Installation: Not affected.

Disassembly/Assembly: Not affected.

Cleaning: Not affected.

Inspection/Check: Not affected.

Repair: Not affected.

Testing: Not affected.

(5) Supplemental Information

None.

### D. <u>Description</u>

New improved packings are provided to replace certain discontinued packings.

#### E. Compliance

Category 7

Accomplish when supply of superseded parts has been depleted.

## F. Approval Data

The part number changes shown in the Material Information section have been shown to comply with applicable Federal Aviation Regulations and are FAA-APPROVED for the engine model(s) listed.

The compliance statement and the procedures described in this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

Printed in Great Britain

May 28/04 R Jul.25/06



R G. Material - Price and Availabil	.ity	/
-------------------------------------	------	---

- R (1) The estimated price of each new part is listed in the supplement to this B bulletin.
- R (2) There is no kit provided to do this Service Bulletin.
- R (3) Part availability information is provided in material data Instructions Disposition.

## H. <u>Tooling - Price and Availability</u>

R Special tools are not required to accomplish this Service Bulletin.

#### I. References

Printed in Great Britain

R

- R (1) V2500 Service Bulletin:
- R V2500-ENG-72-0132 ENGINE LP COMPRESSOR REMOVAL OF STAGE 6 BUFFER AIR SYSTEM
- R (2) V2500 Engine Illustrated Parts Catalogs (S-V2500-1IA, S-V2500-2IA, S-V2500-2IB, S-V2500-3IA, S-V2500-3IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA and S-V2500-7IB), Chapter/Section R follows:
- R 72-32-20 Figure 1 Item 20
- R 72-32-25 Figure 2 Item 350
- R 72-32-53 Figure 1 Item 400
- R 72-42-30 Figure 1 Item 10
- R 72-50-53 Figure 20 Item 300
- R 72-50-53 Figure 20 Item 570
- R 72-58-02 Figure 01 Item 040
- R 72-58-02 Figure 1 Item 80
- R 73-11-41 Figure 1 Item 10
- R 73-11-41 Figure 2 Item 1
- R 73-11-41 Figure 3 Item 1
- R 79-21-49 Figure 16 Item 117
- R (3) Internal Reference No. 03VB017, 03VB017A, 03VB017B, 03VB17C, 03VB017D.

May 28/04 R Jul.25/06



R

#### SERVICE BULLETIN

R (4) ATA Locator - 72-32-00, 72-42-00, 72-50-00, 72-58-00, 73-11-00, 79-21-00.

## J. Other Publications Affected

- (1) V2500 Engine Illustrated Parts Catalogs (S-V2500-1IA, S-V2500-2IA, S-V2500-2IB, S-V2500-3IA, S-V2500-3IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA and S-V2500-7IB), to add the new parts, Chapter/Section follows:
- R 72-32-20 Figure 1 Item 20
- R 72-32-25 Figure 2 Item 350
- R 72-32-53 Figure 1 Item 400
- R 72-42-30 Figure 1 Item 10
- R 72-50-53 Figure 20 Item 300
- R 72-50-53 Figure 20 Item 570
- R 72-58-02 Figure 01 Item 040
- R 72-58-02 Figure 1 Item 80
- R 73-11-41 Figure 1 Item 10
- R 73-11-41 Figure 2 Item 1
- R 73-11-41 Figure 3 Item 1
- R 79-21-49 Figure 16 Item 117

#### K. Interchangeability of Parts

Old and new parts are directly interchangeable.

## L. <u>Information in the Appendix</u>

Alternate Accomplishment Instructions (No)

Progression Charts (Yes)

Added Data (No)

Revision to Table of Limits (No)

Inspection Procedures (No)

May 28/04 R Jul.25/06



## M. General Information

The Material Information section of this Service Bulletin provides the latest information concerning the availability of the affected parts.

May 28/04 R Jul.25/06



## 2. Material Information

## A. Industry Support Program

Not Applicable.

## B. The material data that follows is for each engine.

For V2500-A1, V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5, V2530-A5, V2533-A5, V2525-D5, V2528-D5 Engines:

FIG NEW ITEM PART NO. NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
72-32-20 01-100 ST1946-276	1	Packing, Preformed	AS3209-276	(2)(B)(I)
72-32-25 02-350 ST1946-265	1	Packing, Preformed	AS3209-265	(2)(B)(I)
72-32-53 01-400 ST1946-279	1	Packing, Preformed	AS3209-279	(2)(B)(I)
72-42-30 01-010 ST1946-027	1	Packing, Preformed	AS3209-027	(2)(B)(I)
72-50-53 20-300 ST1946-014 20-570 ST1946-015	1	Packing, Preformed Packing, Preformed	AS3209-014 AS3209-015	
72-58-02 01-040 ST1946-107 01-080 ST1946-110	1	Packing, Preformed Packing, Preformed	AS3209-107 AS3209-110	
73-11-41 01-010 ST1946-010 02-001 ST1946-010 03-001 ST1946-010	18 8 24	Packing, Preformed Packing, Preformed Packing, Preformed	AS3209-010 AS3209-010 AS3209-010	(2)(B)(I)
79-21-49 16-117 ST1946-012	1	Packing, Preformed	AS3209-012	(2)(B)(I)



R For V2500-A1 Engines not incorporating Service Bulletin R V2500-ENG-72-0132:

R FIG NEW QTY PART TITLE OLD INSTR R ITEM PART PART DISP

NO. NO. NO.

R 72-32-53

R

R

Printed in Great Britain

R 01-400 ST1946-280 1 Packing, Preformed AS3209-280 (2)(B1)(I)

## C. <u>Instructions/Disposition Code Statements:</u>

Parts Modification Conditions

(2) The new part is a replacement part only, and cannot be obtained by modification of the old part.

Spare Parts Availability

(B) The new part will be available approximately February 2004 (B1) The new part will be available approximately August 2006

Cleaning, Inspection and Repair Information

(I) The cleaning, inspection and repair requirements are the same for the old and new part. The applicable engine manuals will be revised.

### 3. Accomplishment Instructions

- A. None
  - (1) Recording Instructions
    - (a) A record of accomplishment is not required.

May 28/04 R Jul.25/06





# APPENDIX 1


Parts Progression To Show the Changed Part in Relation to Other Parts

May 28/04 R Jul.25/06



**MODIFICATIONS** 

PART NUMBER CHANGE



R

- (1) For all A5/D5 Engines and for A1 engines incoporating SB 72-0132.
- (2) For A1 Engines only not incorporating SB 72-0132.

pw0b513641a

R FAMILY TREE - PREFORMED PACKINGS CATALOG SEQUENCE 72-32-20 FIG 01 ITEM 100, 72-32-25 FIG 02 ITEM 350 AND 72-32-53 FIG 01 ITEM 400.


R Chart A Sheet 1

May 28/04 R Jul.25/06



**MODIFICATIONS** 

#### PART NUMBER CHANGE



R

pw0b513719

R FAMILY TREE - PREFORMED PACKINGS CATALOG SEQUENCE 72-42-30 FIG 01 ITEM 100, 72-58-02 FIG 01 ITEM 080.


R Chart A Sheet 2

May 28/04 R Jul.25/06



**MODIFICATIONS** 

PART NUMBER CHANGE



R

pw0b51372

R

R

FAMILY TREE - PREFORMED PACKINGS CATALOG SEQUENCE 73-11-41 FIG 01 ITEM 010 AND 73-11-41 FIG 02 ITEM 001.


Chart A Sheet 3

May 28/04 R Jul.25/06



**MODIFICATIONS** 

PART NUMBER CHANGE



R

pw0b513722

FAMILY TREE - PREFORMED PACKINGS CATALOG SEQUENCE 73-11-41 FIG 03 ITEM 001 AND 79-21-49 FIG 16 ITEM 117.

R R


Chart A Sheet 4

May 28/04 R Jul.25/06



**MODIFICATIONS** 

PART NUMBER CHANGE



R

pw0b514611

R

R

FAMILY TREE - PREFORMED PACKINGS CATALOG SEQUENCE 73-50-53 FIG 20 ITEM 300 AND 72-50-53 FIG 20 ITEM 570.

Chart A Sheet 5

May 28/04 R Jul.25/06



## INFORMATION - ENGINE - PROVIDE IMPROVED PREFORMED PACKINGS

#### SUPPLEMENT - PRICES AND AVAILABILITY

The prices (if shown) are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

The estimated price of new material to do this Service Bulletin using new R replacement parts is \$275.10.

# 1. Modification Kit:

Not applicable.

## 2. Parts required:

	Part No.	Description	Unit Price US Dollars
R	ST1946-010	Packing, Preformed	1.50
R	ST1946-012	Packing, Preformed	5.00
R	ST1946-014	Packing, Preformed	1.60
R	ST1946-015	Packing, Preformed	4.70
	ST1946-027	Packing, Preformed	4.50
	ST1946-107	Packing, Preformed	4.50
	ST1946-110	Packing, Preformed	1.50
	ST1946-265	Packing, Preformed	35.00
	ST1946-276	Packing, Preformed	40.00
	ST1946-279	Packing, Preformed	55.00
R	ST1946-280	Packing, Preformed	51.60

