400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600 P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

DATE: Feb.27/04

V2500-A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin EV2500-70-0858

Bulletin Initial Issue

Remove Incorporate

Pages 1 to 5 of the Service Bulletin

Reason for change Initial issue

V2500-ENG-70-0858

Printed in Great Britain

Printed in Great Britair

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	Revision	Number	Revision	Date

Bulletin	
1	Feb.27/04
2	Feb.27/04
3	Feb.27/04
4	Feb.27/04
5	Feb.27/04

<u>INFORMATION - ENGINE - LP COMPRESSOR - TO USE SPECIFIC ENGINE PARTS IN V2533-A5</u> <u>ENGINES</u>

1. Planning Information

- A. Effectivity
 - (1) Airbus A321

V2533-A5 Engines

B. Concurrent Requirements

None.

- C. Reason
 - (1) Problem

A customer requested to fit P/N 5A1424 Fan Frame from a V2530-A5 Engine to V2533-A5 Engine Serial No. V10787. The applicabilities of P/N 5A1424 Fan Frame are V2522-A5, V2524-A5, V2527-A5, V2527E-A5, V2527M-A5 and V2530-A5. The Engine model of V10787 is V2533-A5. The current applicability of the Fan Frame (P/N 5A1424) does not satisfy the use of this Fan Frame into a V2533-A5 Engine.

(2) Background

See (1) Problem.

(3) Objective

The purpose of this Service Bulletin is to allow the use of P/N 5A1424 Fan Frame and the associating parts into V2533-A5 engines when required.

(4) Substantiation

The design of the 5A1424 Fan Frame satisfies that Fan Frames can be installed to the V2533-A5 engines for service.

- (5) Effect of Bulletin on:
 - (a) Removal/Installation

Not affected.

(b) Disassembly/Assembly

Not affected.

Feb.27/04 Feb.27/04

(c) Cleaning

Not affected.

(d) Inspection/Check

Not affected.

(e) Repair

Not affected.

(f) Testing

Not affected.

(6) Supplemental Information

None.

D. Description

None.

E. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

F. Approval

The part number changes and/or part modification described in Section 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Models listed.

G. Manpower

Estimated Man-hours to incorporate the full intent of this Service Bulletin:

(1) In service

Not applicable.

(2) At overhaul

Not applicable.

<u>NOTE</u>: The parts affected by this Service Bulletin are accessible at overhaul.

Feb.27/04 Feb.27/04



H. Weight and Balance

(1) Weight Change

None.

(2) Moment Arm

None.

(3) Datum

Engine front mount centreline (Power Plant Station - (PPS) 100).

I. Electrical Load Data

The aircraft electrical load is not affected by this Service Bulletin.

J. Software Accomplishment Summary

Not applicable.

K. References

- (1) IAE Engineering Change No. 03VJ022.
- (2) ATA Locator 72-32-00.

L. Other Publications Affected

(1) V2500 Engine Illustrated Parts Catalogue (EIPC, S-V2500-5IA) Chapter/Section 72-32-03 and 72-32-38 will be revised to incorporate the new part number.

M. <u>Interchangeability of Parts</u>

Not affected.

2. Material Information

A. <u>Material - Price and Availability</u>

Not applicable.

B. <u>Industry Support Information:</u>

None.

C. <u>Kits necessary for this Service Bulletin:</u>

None.

D. Parts affected by this Service Bulletin:

V2533-A5 Engines

NEW

72-32-00

FIG

	ITEM NO.	PART NO.				PART NO.	DISP
	02215	4W0110	1	.Bolt, Machine Double Hex	-	-	(A)
	02220	AS43013-108	1	.Ring, Sealing Toroidal	-	-	(A)
72-32-03							
	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
	03100 03141 03890	5A1424 AGS3731 5A1315	1 1 3	.Frame, A/O FanInsert, Screw ThreadThermocouple, A/O T2.5CM	- - -	- - -	(A) (A) (A)

QTY PART TITLE

72-32-38

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
01200	5A0805	1	.Tube, A/O Seal Drain	_	_	(A)

Feb.27/04 Feb.27/04 V2500-ENG-70-0858

MAT OLD

INSTR



- E. <u>Instructions disposition codes:</u>
 - (A) New parts can be applicable to V2533-A5 engines.
- F. Tooling Price and Availability:

Not applicable.

3. Accomplishment Instructions

A. Rework Instructions

Not applicable.

B. Assembly Instructions

Not applicable.

C. Recording Instructions

Not applicable.

