



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Jan.10/07

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0901

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 4 of the Service Bulletin	Reason for change Initial Issue
--------	--	------------------------------------

V2500-ENG-70-0901
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Jan.10/07
--	--	-----------

2		
---	--	--

		Jan.10/07
--	--	-----------

3		
---	--	--

		Jan.10/07
--	--	-----------

4		
---	--	--

		Jan.10/07
--	--	-----------

Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE INTRODUCTION OF A NEW IMPROVED HYDRAULIC
PRESSURE SWITCH

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
 - (a) ALL V2500-A1 Engines.
 - (b) V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Engines.

B. Reason

A new Hydraulic Pressure Switch with improved reliability has been introduced.

C. Compliance

Category Code 8

Accomplish based upon experience with prior configuration.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

E. References

- (1) IAE Engineering Change No. 05VN315.
- (2) ATA Locator 29-11-17.
- (3) Airbus Aircraft modification No. 35479.

F. General Information

- (1) The shape, weight, interfaces and performance of the new improved Hydraulic Pressure Switch are not affected.



- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of the new Hydraulic Pressure Switch.
- (3) Publications affected
 - (a) The A320/V2500-A1 Engine Illustrated Parts Catalog (S-V2500-1IA) will be revised to include the new parts. See "Material Information" section for ATA Locations.
 - (b) All V2500-A5 Engine Illustrated Parts Catalogs will be revised to include the new parts. See "Material Information" section for ATA Locations.

2. Material Information

A. Part Prices:

Not Applicable.

B. Parts affected by this Service Bulletin:

Applicability: For each V2500-A1 and V2500-A5 Engine to incorporate this Bulletin.

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
29-11-17						
01-010	450-1- 3100-00	1	LP Warning Switch	-	50-1- 3100-00	(A)(S1)

C. Instruction/Disposition Codes:

(A) New part is currently available.

(S1) New and old parts are freely and fully interchangeable.

3. Accomplishment Instructions.

None.