



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Oct.28/08

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin V2500-ENG-70-0903

Service Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 4 of the Service Bulletin	Initial Issue.

V2500-ENG-70-0903

Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF NEW BACKSHELLS FOR THE GENERAL
SERVICES HARNESS

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
 - (a) V2500-A1 Engines.
 - (b) V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Engines.

B. Reason

- (1) To announce the availability of new General Services Harness – Backshells, which provide less restrictive cable entry compared to the existing General Services Harness – Backshells.

C. Compliance

- (1) Not applicable.

D. Approval

- (1) The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.
- (2) The authorising IAE document is EC 06VN306.

E. General Information

- (1) This General Information Bulletin introduces new Backshells as replacements for the existing Backshells used on the General Services Harness only.

(2) Publications affected

- (a) The V2500-A1/A5 Engine Illustrated Parts Catalogs (S-V2500-1IA, S-V2500-2IA, S-V2500-2IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB) will be revised to include the new Backshells. Refer to Section 2. "Material Information" for ATA Locations.

F. References

- (1) IAE Engineering Change No. 06VN306.
- (2) ATA Locators 71-51-43.

2. Material Information

A. Part Prices:

Not applicable.

B. Parts affected by this Service Bulletin:

Applicability: For all V2500-A1/A5 Engines

The following parts are affected in the V2500-A1/A5 Engine Illustrated Parts Catalogs:

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
71-51-43						
02-365	388AJ 101M 1810A	1	...Backshell	-	388AJ 101M 1808A	(A)(B) (S1)
02-395	388AJ 101M 1810A	1	...Backshell	-	388AJ 101M 1808A	(A)(B) (S1)

C. Instruction/Disposition Codes:

(A) New part is available.

(B) The old part will no longer be available when stock of the old part is exhausted.

(S1) The old part number may be used as a replacement only where the old part number was installed. The new part is an acceptable replacement for the old or new part number.

3. Accomplishment Instructions

None.