



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Nov.25/08

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A5/D5 SERIES PROPULSION SYSTEM SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin V2500-ENG-70-0951.

Service Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 4 of the Service Bulletin	Initial Issue.

V2500-ENG-70-0951

Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

INFORMATION – LP COMPRESSOR – TO ANNOUNCE THE AVAILABILITY OF REPAIR PARTS FOR REAR
FAIRING

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5 and V2527M-A5 Engines.
- (2) Airbus A320
 - (a) V2524-A5, V2527-A5 and V2527E-A5 Engines.
- (3) Airbus A321
 - (a) V2530-A5 and V2533-A5 Engines.
- (4) Boeing MD-90
 - (a) V2525-D5 and V2528-D5 Engines.

B. Reason

To announce the availability of the repair parts for the rear fairing.

C. Compliance

Category Code 8.

Accomplish based upon experience with the prior configuration.

D. Approval

The part number changes and/or part modifications described in section 2 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

E. General Information

- (1) The Material Information of this Bulletin provides the latest information concerning the availability of the rear fairing pad.



- (2) New Repair Scheme being introduced into the V2500 Engine Manual (E-V2500-1IA and E-V2500-3IA) which requires Special Repair Parts for its accomplishment.

ATA Ref. No.	Repair Scheme	Title
72-32-86	VRS1983	Replace the pads of the rear fairing assembly.

(For Repair Parts required, refer to the "Material Information".)

F. References

- (1) Internal Reference No.:
Engineering Change No. 08VJ002.
- (2) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-86 Figure 1.
- (3) ATA Locator - 72-32-00.

G. Other Publications Affected

- (1) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-86 Figure 1 will be revised.
- (2) V2500 Engine Manual (E-V2500-1IA), Chapter/Section 72-32-86, Inspection/Check-01, Config-03 will be revised.
- (3) V2500 Engine Manual (E-V2500-3IA), Chapter/Section 72-32-86, Inspection/Check-01, Config-02 will be revised.

2. Material Information

A. Parts affected by this Service Bulletin:

Applicability: All V2500-A5/D5 Engines:

The following Repair Part is required to accomplish Repair VRS1983:

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
72-32-86						
01125	5A1925	A/R	Block	-	NNA1616	(A)

B. Instruction/Disposition Codes:

(A) New part is currently available.

3. Accomplishment Instructions

None.