

International Aero Engines

SERVICE BULLETIN

ENGINE - HP TURBINE ROTOR AND STATOR ASSEMBLY - INTRODUCE A REVISED STAGE 2 BLADE RETAINING PLATE - CATEGORY CODE 7 - MOD.ENG-72-0028

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1 Engines before Serial No.V0131, except V0125 and

Serial No.V0139

B. Reason

(1) Condition

Not applicable

(2) Background

The design change will accommodate anticipated additional product improvements.

(3) Objective

To provide a product improvement.

(4) Substantiation

Not considered necessary.

(5) Effect of Bulletin on the following shop functions:

Removal/Installation Not affected Disassembly/Assembly Not affected Cleaning Not affected Inspection/Check Not affected Repair Not affected Testing Not affected

(6) Supplemental Information:

None.

C. <u>Description</u>

(1) A new Stage 2 HPT Blade Retaining Plate is provided.

V2500-ENG-72-0028



SERVICE BULLETIN

D. Approval

The Part Number Changes and/or part modifications described in Sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

F. Manpower

Estimated manhours to incorporate the full intent of this Bulletin:

Venue Estimated Manhours

(1) In Service Not applicable

(2) At overhaul TOTAL 1 hour 13 minutes

(a) To gain access Not applicable

(Parts are accessible at overhaul)

(b) To install the new .. 1 hour 13 minutes stage 2 HPT retaining

ring

TOTAL: 1 hour 13 minutes

(c) To return part to Not applicable overhaul condition

Remarks: No additional time will be required to maintain the new configuration.

G. Material - Price and Availability

- (1) Modification kit not required.
- (2) See "Material Information" section for prices and availability of future spares.

H. Tooling - Price and Availability

Special tools are not required.



International Aero Engines

SERVICE BULLETIN

I. Weight and Balance

(1) Weight change None

(2) Moment arm No effect

(3) Datum Engine front mount centreline (Power Plant Station (PPS) 100)

J. Electrical Load Data

This Service has no effect on the aircraft electrical load.

K. References

(1) Internal Reference No.


88VA169

(2) Other References

V2500 Engine Manual.

L. Other Publications Affected

- (1) The V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-45-33, Figure 1.
- (2) The V2500 Engine Manual, Chapter/Section 72-45-33, Cleaning, to add the new part.
- (3) The V2500 Engine Manual, Chapter/Section 72-45-33, Inspection/Check, to add the new part.
- (4) The V2500 Engine Manual, chapter/Section 72-45-33, Repair, to add the new part.




SERVICE BULLETIN

2. Accomplishment Instructions


- A. Rework Instructions
 - (1) There are no rework instructions necessary to accomplish this Service Bulletin.
- B. Assembly Instructions
 - (1) Install the 2A1813 stage 2 Blade Retaining Plate (1 off) by the approved procedure in Reference (1) Chapter/Section 72-45-30 Assembly. Refer to Figure 1.
- C. Recording Instructions
 - (1) A record of accomplishment is necessary.



SERVICE BULLETIN



REMOVE THE PN 2A0160 STAGE 2 HPT BLADE RETAINING PLATE (1 Off) AND INSTALL THE PN 2A1813 STAGE 2 HPT BLADE RETAINING



de00019537

Location of the stage 2 HPT blade retaining plate Fig.1

V2500-ENG-72-0028



International Aero Engines

SERVICE BULLETIN

3. Material Information

New Est'd Old

Part No. Unit Part No. Instructions (ATA No.) Qty Price (\$) Keyword (IPC No.) Disposition

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kits associated with this Bulletin:

None.

B. Parts affected by this Bulletin:

2A1813 1 Plate - Retaining, 2A0160 (A)(B) (72-45-33) Blade, HPT, Stage 2 (01-020)

C. <u>Instruction/Disposition Code Statements:</u>

- (A) New Part currently available for sale.
- (B) Old Part is no longer available.

NOTE: The estimated 1990 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Pricing Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.