



Service Bulletin No.: V2500-ENG-72-0106

Subject: Cancellation of Engine Service Bulletin V2500-ENG-72-0106
(LP Turbine Assembly - Replacement of LP Turbine Rotor Bolts)

Notice: The content of Service Bulletin V2500-ENG-72-0106, is hereby cancelled.
For record purposes, a copy of this notice, attached to a copy of
Service Bulletin V2500-ENG-72-0106, should be retained on file.

Reason: Enough evidence was gained from parts returned to MTU according to
Service Bulletin V2500-ENG-72-0106. In the mean time the Engine Manual
has been to allow only one time usage for rotor bolts and nuts.

