



International Aero Engines
INFORMATION BULLETIN

Jan. 29/99

Subject: Transmittal of Revision 1 to Non-Modification Service Bulletin V2500-ENG-72-0324.

Service Bulletin Revision History:

Initial Issue	July 21/98.
Revision 1	Jan. 29/99.

Reason for Revision :

(1) To cancel the Initial Issue of Non-Modification Service Bulletin ENG 72-0324.

Effect On Past Compliance:


None.

List of Effective Pages:

<u>Page No.</u>	<u>Revision No.</u>	<u>Effective Page</u>
1 to 4	Revision 1	Jan. 29/99.

V2500-ENG-72-0324

Transmittal
Page 1 of 1



International Aero Engines
INFORMATION BULLETIN

**ENGINE - LUBRICATION PROCEDURE FOR HPC VSV MECHANISM WITH TRI-FLOW
(NON-MODIFICATION)**

MODEL APPLICATION

V2500-D5

BULLETIN INDEX LOCATOR

72-41-00

Compliance Category Code

3


Internal Reference No.

EC98VR796A EC89VR796B

July 21/98
Revision 1 Jan. 29/99

V2500-ENG-72-0324

Page 1 of 4



International Aero Engines

INFORMATION BULLETIN

ENGINE - LUBRICATION PROCEDURE FOR HPC VSV MECHANISM WITH TRI-FLOW (NON-MODIFICATION)

1. Planning Information

A. Effectivity

(1) Aircraft:


- (a) Boeing-Douglas MD-90.

(2) Engines:

- (a) V2525-D5 All engines.
- (b) V2528-D5 All engines.

B. Reason


- (1) The purpose of this issue of Non-Modification Service Bulletin ENG-72-0324 is to cancel the instructions contained in the Initial Issue.
- (2) The content of this Non-Modification Service Bulletin will be included as a TASK in the MD-90 Aircraft Maintenance Manual (AMM).



International Aero Engines
INFORMATION BULLETIN

2. Material Information

Not applicable.



International Aero Engines

INFORMATION BULLETIN

3. Accomplishment Instructions

Not applicable.