



International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - ANNOUNCE THE AVAILABILITY OF VARIOUS INLET COWL
REPAIR PARTS.

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

71-11-00

Compliance Category Code

N/A


Internal Reference No.

90VN529

Dec 9/92

V2500-NAC-70-0150

Page 1 of 4



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - ANNOUNCE THE AVAILABILITY OF VARIOUS INLET COWL REPAIR PARTS.

A. EFFECTIVITY

(1) AIRCRAFT: Airbus A320

(2) NACELLE: V2500-A1

B. REASON

To announce the availability of the required repair procedures and corresponding repair parts for Air Intake Cowl Lip-skins.

C. COMPLIANCE

Category Code N/A

D. APPROVAL

The part number changes shown in paragraph G of this service bulletin have been sanctioned under a product development control system that has been approved by the DGAC (Direction Generale de l'Aviation Civile - France).

E. REFERENCES

(1) IAE Engineering Change No. 90VN529


F. GENERAL INFORMATION

- (1) Part numbers added and changed due to promulgation of the required repair procedures and repair parts for Air Intake Cowl Lip-skins.
- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of required repair parts for Air Intake Cowl Lip-skins.

Dec 9/92

V2500-NAC-70-0150

Page 2 of 4



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

(3) Other publications affected

- (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (b) The V2500 Power Plant Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (c) The V2500 Component Maintenance Manual will be included the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each Nacelle to incorporate this Bulletin.

The following repair parts are required to accomplish Repair Scheme VRS2731, VRS2732 and VRS2851.

| New Part No. (ATA No.) | Qty | Est'd Unit Price (\$) | Keyword | Old Part No. (IPC No.) | Supply Status |
|----------------------------|-----|--------------------------|---------|---------------------------|------------------|
| 740-3004-503 (71-11-11) | 1 | RQ* | Lipskin | 740-3004-501 (03-710) | (A) |
| CR2238-3-3 (71-11-11) | A/R | \$ 12.00 | Rivet | - (03-712) | (A) |
| CR2238-3-4 (71-11-11) | A/R | \$ 12.00 | Rivet | - (03-713) | (A) |
| CR2238-3-5 (71-11-11) | A/R | \$ 12.00 | Rivet | - (03-714) | (A) |
| CR2238-6 (71-11-11) | A/R | \$ 12.00 | Rivet | - 03-715) | (A) |
| CR2238-3-7 (71-11-11) | A/R | \$ 12.00 | Rivet | - (03-716) | (A) |
| MS20246DD6 (71-11-11) | A/R | \$ 12.00 | Rivet | - (03-718) | (A) |


RQ* = Quote only basis.

A/R = As Required.

Dec 9/92

V2500-NAC-70-0150

Page 3 of 4



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

(A) The new parts are currently available.

NOTE: The estimated 1992 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.

Dec 9/92

V2500-NAC-70-0150

Page 4 of 4