

International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - ANNOUNCEMENT OF THE AVAILABILITY OF SERVICE
REPAIR PARTS FOR THE OIL FILLER ACCESS DOOR
HINGE OF THE LH FAN COWL DOOR.

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

71-13-00

Compliance Category Code

7


Internal Reference No.

89VN557

Dec 9/92

V2500-NAC-70-0176

Page 1 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

**INFORMATION - ANNOUNCEMENT OF THE AVAILABILITY OF SERVICE
REPAIR PARTS FOR THE OIL FILLER ACCESS DOOR HINGE
OF THE LH FAN COWL DOOR.**

A. EFFECTIVITY

- (1) AIRCRAFT: Airbus A320
- (2) NACELLE: V2500-A1

B. REASON

To announce the introduction of service repair parts for the oil filler access door hinge of the LH Fan Cowl door.

C. COMPLIANCE

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

D. APPROVAL

The part numbers reflected in paragraph G of this service bulletin have been sanctioned under a product development control system that has been approved by the DGAC (Direction Generale de l'Aviation Civile -France).

E. REFERENCES

- (1) IAE Engineering Change No. 89VN557.


F. GENERAL INFORMATION

- (1) Part numbers added due to introduction of service repair parts for the oil filler access door hinge of the LH Fan Cowl door.
- (2) The Material Information portion of this bulletin provides the latest information concerning the availability of the service repair parts for the oil filler access door hinge of the LH Fan Cowl door.

Dec 9/92

V2500-NAC-70-0176

Page 2 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

(3) Other publications affected

- (a) The V2500 Engine Illustrated parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (2) The V2500 Power Plant Illustrated parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.
- (3) The V2500 Component Maintenance Manual will be included the new parts. See "Material Information" Section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this Bulletin.

The following repair parts are required to accomplish Repair Scheme VRS2849.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
740-4086-503 (71-13-14)	1	RQ*	Hinge	- (01-110)	(A)
HL11VF6-6 (71-13-14)	12	RQ*	Pin	- (01-115)	(A)
HL97V6 (71-13-14)	12	RQ*	Collar	- (01-120)	(A)
AN960C10L (71-13-14)	12	\$1.00	Washer	- (01-125)	(A)

RQ* = Quote only basis.

(A) New parts are currently available.

NOTE: The estimated 1992 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Parts Sales Department for information concerning firm price.

Dec 9/92

V2500-NAC-70-0176

Page 3 of 3