

International Aero Engines

INFORMATION BULLETIN

STANDARD PRACTICES - ENGINE - INFORMATION - NACELLE - ELECTRICAL POWER - TO ANNOUNCE

THE AVAILABILITY OF REPAIR PARTS FOR IDG CABLE REPLACEMENT. - NOT APPLICABLE
MOD.NAC-70-0271

1. Planning Information

A. EFFECTIVITY

(1) AIRCRAFT: Airbus A320

(2) NACELLE: V2500-A1

B. REASON

To introduce the repair parts required to accomplish Repair Scheme VRS2926 for IDG cable replacement repair part.

C. <u>Compliance</u>

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

D. APPROVAL

The change in definition of this Service Bulletin has been covered by an aircraft modification approved by the DGAC (Direction Generale de L'Aviation Civile - France).

E. References

(1) Internal Reference No.

89VN566

F. GENERAL INFORMATION

- (1) The Material Information portion of this bulletin provides the latest information concerning the availability of repair parts for IDG cable replacement.
- (2) Other publications affected
 - (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" Section for ATA Locations.
 - (b) The V2500 Component Maintenance Manual will be included the new parts. See "Material Information" Section for ATA Locations.

V2500-NAC-70-0271

International Aero Engines

INFORMATION BULLETIN

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this bulletin.

(1) The following repair parts are required to accomplish Repair Scheme VRS2926.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
031-1194-000	4	\$228.00	Contact	(01–900)	(A)
M22759-3-02-9 (24-21-43)	4	RQ*	Wire	(01–908)	(A)
K973 (24-21-43)	4	\$ 5.00	Terminal Lug		(A)

RQ* = Quote only basis

NOTE: The estimated 1994 Unit Price shown is provided for planning purposes only and do not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.