



International
Aero Engines

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

INFORMATION - NACELLE - TO ANNOUNCE THE AVAILABILITY OF REPAIR
PARTS FOR THE REPAIR OF THE LEFT AND
RIGHT HAND FAN COWL DOOR OUTLET
GRILLES

MODEL APPLICATION

V2500-A1

BULLETIN INDEX LOCATOR

71-00-00

Compliance Category Code

8


Internal Reference No.

90VN593

August 28, 1997

V2500-NAC-70-0357

Page 1 of 3



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

**ANNOUNCEMENT - NACELLE - TO ANNOUNCE THE AVAILABILITY OF
REPAIR PARTS FOR THE REPAIR OF THE
LEFT AND RIGHT HAND FAN COWL DOOR
OUTLET GRILLES**

A. EFFECTIVITY

(1) AIRCRAFT: Airbus A320

(2) NACELLE: V2500-A1

B. REASON

To introduce fan cowl door outlet grille replacement parts.

C. COMPLIANCE

Category Code 8

Accomplish based upon experience with prior configuration.

D. APPROVAL

The part number transaction shown under the "MATERIAL INFORMATION" portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. REFERENCES

(1) IAE Engineering Change No. 90VN593.


F. GENERAL INFORMATION

(1) The Material Information of this bulletin provides the latest information concerning the availability of fan cowl door outlet grille replacement parts.

August 28, 1997

V2500-NAC-70-0357

Page 2 of 4



**International
Aero Engines**

V2500 Propulsion System — Nacelle General

INFORMATION BULLETIN

(2) Other publications affected

- (a) The V2500-A1 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA locations.
- (b) The V2500-A1 Power Plant Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this bulletin.

(1) The following repair parts are required to accomplish Repair Scheme VRS2959

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
740-4035-501 (71-13-11)	1		Grille	--- (01-745)	(A)
HL9V-6 (71-13-11)	46		Collar	--- (01-747)	(A)

(1) The following repair parts are required to accomplish Repair Scheme VRS2963

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
740-4035-502 (71-13-16)	1		Grille	--- (01-745)	(A)
HL97V-6 (71-13-16)	46		Collar	--- (01-747)	(A)

(A) The new parts are currently available.

NOTE: The estimated 1997 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.

August 28, 1997

V2500-NAC-70-0357

Page 3 of 3

