



400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE:- 860 565 5515  
FAX:- 860 565 0600

DATE: Apr. 6/09

P.O. BOX 31, DERBY  
TELEGRAMS - 'ROYCAR' DERBY  
TELEX - 37645  
TELEPHONE:- 44 (0) 1332 242424  
FAX:- 44 (0) 1332 249936

Printed in Great Britain

## V2500-D5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin V2500-NAC-70-0679

### Service Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 3 of the Service Bulletin.	Initial Issue.

**V2500-NAC-70-0679**  
Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED  
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England  
© Rolls-Royce plc (date as above) Printed in Great Britain



INFORMATION – NACELLE – ANNOUNCEMENT OF THE AVAILABILITY OF THE NEW LOCKING ACTUATOR  
PROXIMITY SWITCH ASSEMBLY

1. Planning Information

A. Effectivity

- (1) Aircraft
  - (a) Boeing MD-90.
- (2) Nacelle
  - (a) V2500-D5.

B. Reason

To announce the availability of a new locking actuator proximity switch assembly.

C. Compliance

Category Code 7.

Accomplish when supply of superseded parts has been depleted.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

The authorising IAE document is EC 99VN800B.

The part number changes and/or part modification described in Section 2 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. General Information

- (1) IAE Engineering Change No.:  
99VN800B.
- (2) ATA Locator – 78-30-00 (CMM).
- (3) Publications affected:
  - (a) The V2500 Thrust Reverser Component Maintenance Manual (CMM-TR-V2500-3IA) will be revised to include the new part. Refer to Section 2. "Material Information" for ATA locations.

## 2. Material Information

### A. Part Prices:

Not applicable.

### B. Parts affected by this Service Bulletin:

Applicability: For each V2500-D5 Thrust Reverser Assembly.

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
78-30-00 (CMM)						
24-650	8-527-03	1	..Switch Assy	-	8-527-01	(A) (S1)
25-650	8-527-03	1	..Switch Assy	-	8-527-01	(A) (S1)

### C. Instruction/Disposition Codes:

(A) New part is currently available.

(S1) New and old parts are freely and fully interchangeable.

3. Accomplishment Instructions

None.

Printed in Great Britain