



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Jan. 4/07

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin NV2500-70-0751

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 4 of the Service Bulletin	Reason for change Initial Issue
--------	--	------------------------------------

V2500-NAC-70-0751
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		Jan.4/07
2		Jan.4/07
3		Jan.4/07
4		Jan.4/07

Printed in Great Britain

V2500-NAC-70-0751
Transmittal - Page 2

INFORMATION – NACELLE – TO ANNOUNCE THE AVAILABILITY OF A NEW IMPROVED OIL FILL
ACCESS DOOR ON THE LEFT FAN COWL DOOR

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Nacelles.
- (2) Airbus A320
 - (a) V2500-A1 Nacelles.
 - (b) V2527-A5, V2527E-A5 Nacelles.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Nacelles.

B. Reason

To announce the availability of a new improved Oil Fill Access Door on the Left fan cowl door.

C. Compliance

Category Code 7.

Accomplish when the supply of superseded parts has been depleted.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

E. References

- (1) IAE Engineering Change No. 04VN751 issue 1.
- (2) Shorts modification No. D1148.
- (3) Airbus Aircraft modification No. 36822/P9584.
- (4) ATA Locators 71-13-00, 71-13-11 and 71-13-14.

F. General Information

- (1) This General Information Bulletin introduces a new improved Oil Fill Access Door on the left fan cowl door. The new Oil Fill Access Door is now manufactured as a one-piece composite laminate panel.
- (2) Publications affected:
 - (a) V2500-A1/A5 Engine Illustrated Parts Catalogs will be revised to include the new Oil Fill Access Door. See Information section for ATA locations.
 - (b) The A320/V2500-A1, A319/A320/A321/V2500-A5 Component Maintenance Manual will be revised to include the new Oil Fill Access Door. See Information section for ATA locations.

2. Material Information

A. Part Prices:

Not applicable.

B. Parts affected by this Service Bulletin:

Applicability: For all V2500-A1/A5 Nacelles.

The following parts are affected in the V2500-A1/A5 Engine Illustrated Parts Catalogs:

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
71-13-11						
01-010	745-4001- 511	1	.Cowl, Left Fan	-	745-4001- 507	(A)(S1)
71-13-14						
01-005	745-4043- 505	1	..Door Assy, Oil Filler Access	-	745-4043- 503	(A)(S1)

The following parts are affected in the V2500-A1/A5 Component Maintenance Manual:

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
71-13-00						
13070C	745-4043- 505	1	.Door Assy, Oil Filler Access	-	745-4043- 503	(A)(S1)
13001	745-4001- 511	1	Cowl Assy, Left Fan Door	-	745-4001- 507	(A)(S1)

C. Instruction disposition codes:

(A) New parts are available.

(S1) New part coded (S1) is fully and freely interchangeable with old part coded (S1).

3. Accomplishment Instructions.

None.