



400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE:- 860 565 5515  
FAX:- 860 565 0600

DATE: Apr.28/08

P.O. BOX 31, DERBY  
TELEGRAMS - 'ROYCAR' DERBY  
TELEX - 37645  
TELEPHONE:- 44 (0) 1332 242424  
FAX:- 44 (0) 1332 249936

## V2500-A5 SERIES PROPULSION SYSTEM SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin V2500-NAC-70-0843

### Service Bulletin Initial Issue

Remove	Incorporate	Reason for change
	Pages 1 to 4 of the Service Bulletin	Initial Issue.

**V2500-NAC-70-0843**  
Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED  
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England  
© Rolls-Royce plc (date as above) Printed in Great Britain



INFORMATION – COMMON NOZZLE ASSEMBLY – ANNOUNCEMENT OF NEW LOWER STRUT ASSY1. Planning InformationA. Effectivity

- (1) Airbus A319
  - (a) V2522-A5, V2524-A5, V2527M-A5 Nacelles.
- (2) Airbus A320
  - (a) V2527-A5, V2527E-A5 Nacelles.
- (3) Airbus A321
  - (a) V2530-A5, V2533-A5 Nacelles.

B. Reason

This conversion to a one piece casting reduces the assembly time and manufacturing hours and maintains interchangeability at the lower strut assy level with a 0.75 lb weight reduction per nacelle.

C. Compliance

Category Code 7.

Accomplish when supply of superseded parts has been depleted.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

The authorising IAE document is EC 01VN605.

In addition, the part number changes and/or part modifications that are given in sections 2 and 3 of this Service Bulletin comply with the applicable Federal Aviation Authority Regulations and are FAA approved for the engine models listed.

E. References

- (1) IAE Engineering Change No. 01VN605.
- (2) AIRBUS Aircraft Modification No. 24259/P8002
- (3) ATA Locators, 78-11-11.

**F. General Information**

- (1) Part numbers changed due to the introduction of new Strut Assembly.
- (2) Publications affected:
  - (a) The V2500 Common Nozzle Component Maintenance Manual (CMM-CNA-V2500-1IA) will be revised to include the new parts. See "Material Information" section for ATA locations.

## 2. Material Information

### A. Part Prices:

Not applicable.

### B. Parts affected by this Service Bulletin:

Applicability: For each V2500-A5 Common Nozzle Assembly.

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
78-11-11						
11-530	745-1102 -505	1	Strut Assy	-	.745-1102 (A)(S1) -503	
06-590	745-1148 -501	1	Strut Assy	-	.745-1105 (A)(S1) -501	

### C. Instruction/Disposition Codes:

(A) New parts are available.

(S1) Old and new part numbers are freely and fully interchangeable.

**3. Accomplishment Instructions.**

None.