



STANDARD PRACTICES – ENGINE – INFORMATION – PROVIDE ALTERNATE SCREWS ATTACHING THE FAN
CASE LINER PANELS AND THE PANEL RUBBER SEALS TO THE FAN CASE – CATEGORY CODE 8 –
MOD.ENG-70-0017

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To announce the availability of alternate Screws attaching the Fan Case Liner Panels and the Panel Rubber Seals to the Fan Case.

C. Compliance

Category code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

(1) Internal Reference No.

88VJ695

F. General Information

The Material Information portion of this Bulletin provides the latest information concerning the availability of the Screws.

V2500-ENG-70-0017



International Aero Engines
INFORMATION BULLETIN

2. Accomplishment Instructions


Not applicable.

Printed in Great Britain

V2500-ENG-70-0017

Jul.28/89

Page 2



International Aero Engines
INFORMATION BULLETIN

3. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
------------------------------	-----	-----------------------------	---------	------------------------------	-----------------------------

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kits associated with this Bulletin:

None

B. Parts affected by this Bulletin:

AS51015 (72-32-00)	27	1.83	Screw, 100 Degree CSK	NAS1102E4 R15 (02-820)	(A)(B)(1)
AS51015 (72-32-00)	20	1.83	Screw, 100 Degree CSK	NAS1102E4 R15 (02-825)	(A)(B)(1)
AS51015 (72-32-00)	11	1.83	Screw, 100 Degree CSK	NAS1102E4 R15 (02-830)	(A)(B)(1)

C. Instruction/Disposition Code Statements:

- (A) New part is currently available.
- (B) Old part will continue to be available for sale.
- (1) Old and new parts are freely and fully interchangeable, both physically and functionally.

NOTE: The estimated 1989 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Contact IAE's Spare Parts Department for information concerning firm prices.

V2500-ENG-70-0017

Jul.28/89

Page 3

