



STANDARD PRACTICES - ENGINE - INFORMATION - PROVIDE ALTERNATE IGNITOR MOUNT BRACKETS
AND ATTACHING HARDWARE - NOT APPLICABLE - MOD.ENG-70-0019

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1

B. Reason

To inform that new ignitor mount brackets and attaching hardware are introduced as alternative parts.

C. Compliance

This Bulletin is introduced for record purposes only.

D. Approval

The part number transactions shown under the Material Information paragraph have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- (1) Internal Reference No.

EC88VJ198C

EC88VJ675

F. General Information

- (1) Alternate standard washers are introduced in place of peculiar washers.
- (2) Alternate ignitor mount brackets made of forgings are introduced.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
------------------------------	-----	-----------------------------	---------	------------------------------	-----------------------------

Applicability: For each V2500 Engine to incorporate this Bulletin.

V2500-ENG-70-0019



International Aero Engines
INFORMATION BULLETIN

5T0053 (72-41-00)	REF	-	Bracket	5T8169 (03-280)	(A)(1)(B)
5T0054 (72-41-00)	REF	-	Bracket	5T8171 (03-310)	(A)(1)(B)
5T0051 (74-11-38)	REF	-	Bracket	5T0032 (01-200) (01-600)	(A)(1)(B)
4W2622 (74-11-38)	REF	4.14	Washer	5T0012 (01-381) (01-779)	(A)(1)(B)

NOTE: The estimated 1989 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Contact IAE's Spare Parts Sales Department for information concerning firm prices.

H. Instruction/Disposition Code Statements

- (A) New parts are currently available as alternative parts to old parts.
- (B) Old parts will continue to be available for sale.
- (1) Old and new parts are freely and fully interchangeable.

Printed in Great Britain

V2500-ENG-70-0019