

## International Aero Engines

## INFORMATION BULLETIN

STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE BUSH HELICOIL INSERT PART NUMBERS - NOT APPLICABLE - MOD.ENG-70-0031

## 1. Planning information

## A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

#### B. Reason

To announce the introduction of alternate Bush Helicoil Inserts.

#### C. <u>Compliance</u>

Not applicable

## D. Approval

(1) The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

## E. References

(1) Internal Reference No.

89VJ020

#### F. General Information

The Material Information portion of this Bulletin provides the latest information concerning the availability of the Helicoil Inserts.

#### G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
MS21209F4- 25L (24-21-42)	1	0.95	Insert, Helicoil	MS21209F4- 25 (01-127)	(A) (B) (1) (2)
MS21209F4- 25L (24-21-42)	1	0.95	Insert, Helicoil	MS21209F4- 25 (01-172)	(A) (B) (1) (2)

V2500-ENG-70-0031

# .....

# INFORMATION BULLETIN

International Aero Engines

## A. <u>Instruction/Disposition Code Statements:</u>

- (A) New Part No. is currently available.
- (B) Old Part No. will continue to be available for sale.
- (1) Old and New parts are freely and fully interchangeable, both physically and functionally.
- (2) New part is an alternate to old part.

NOTE: The estimated 1989 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Contact IAE's Spare Parts Sales Department for information concerning firm prices.