

#### International Aero Engines

## STANDARD PRACTICES - ENGINE - INFORMATION - ADD A REVISED PART NUMBER IDENTIFICATION TO THE EXISTING P2/T2 SENSOR - NOT APPLICABLE - MOD.ENG-70-0042

#### 1. Planning Information

#### A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

#### B. Reason

A unique part number P2/T2 Sensor is provided to make inventory control easier.

#### C. <u>Compliance</u>

For information only

#### D. Approval

The part number transaction shown under sub-paragraph (1) of the "MATERIAL INFORMATION" portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

#### E. References

(1) Internal Reference No.

EC88VA308

#### F. General Information

- (1) The PN2AO528 P2/T2 Sensor is provided as a replacement for the PN1A7734 P2/T2 Sensor.
- (2) Other Publications Affected:
  - (a) The V2500 Engine Illustrated Parts Catalog will be revised to show the new part number.

# **INFORMATION BULLETIN**

International Aero Engines

## 2. Accomplishment Instruction

Not applicable.



#### International Aero Engines

## INFORMATION BULLETIN

#### 3. <u>Material Information</u>

New Est'd Old

Part No. Unit Part No. Instructions (ATA No.) Qty Price (\$) Keyword (IPC No.) Disposition

Applicability: For each V2500 Engine to incorporate this Bulletin.

2A0528 1 - Sensor, P2/T2 1A7734 (A)(B)(C)(D)

(73–22–11) (01–010)

#### A. <u>Instruction/Disposition Code Statements:</u>

(A) New part is currently available.

(B) Old part number will no longer be available.

(C) Old part and new part are directly interchangeable.

(D) Get PN2AO258 Sensor directly from:

Rosemount Inc. 12001 W. 78th St. Eden Prairie, MN 55344-3620 P/L #154DB3

NOTE: The estimated 1989 Unit Prices shown are provided for planning purposes only and do not constitute a firm quotation. Contact IAE's Spare Parts Sales Department for information concerning firm prices.

