

STANDARD PRACTICES - ENGINE - INFORMATION - TO ANNOUNCE VARIOUS ALTERATIONS OF PARTS
SPAREABILITY CODES - NOT APPLICABLE - MOD.ENG-70-0075

Printed in Great Britain

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A320

(2) Engine: V2500-A1

B. Reason

To provide field notification concerning various alterations of parts spareability codes.

C. Compliance

Not applicable

D. Approval

The part number changes described in Sections 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

(1) Internal Reference No.

86VJ054-03

86VJ060-03

86VJ064-01

86VJ086-04

87VJ091-01

87VJ126-01


87VJ133-02

87VJ140-01

87VJ182-03

87VJ220-01

V2500-ENG-70-0075



87VJ232-01

87VJ319-02

88VJ388-01

87VJ197-02

88VJ198A-03

88VJ310-01

88VJ420-03

88VJ626-04

88VJ632-01

88VR013-01

F. General Information

- (1) The spareability of the following parts has been changed to both maintenance and overhaul use.


PNs. 5T8123 (72-00-50, 01-330), 5R0477 (72-00-60, 01-410), 5R0480 (01-550), 5R0477 (01-560), 5R0479 (01-700), 5R0478 (01-710), 5R0002 (72-32-00, 01-310), 5R0003 (01-315), 5R0012 (72-32-89, 01-100), 5W8355 (72-41-34, 01-720), 4W0001 (74-21-43, 01-156), 4W0164 (75-22-41, 01-315), 5T8266 (79-21-43, 01-115), 0F25-009 (01-147), 0F25-021 (01-149), MS9954-06 (01-157), 0F25-021 (01-159), 0F25-014 (01-171), 5T8248, 5T8249 (01-300), 4W0002 (01-310), 5T8080 (01-380), 5T8222 (01-420), 4W0003 (01-430), AS22622 (01-435), 5T8020 (01-440), 5T8075 (01-505), 4W0002 (01-515), 4W0165 (01-520), 4W0002 (01-530), 4W0204 (01-535), 5T8078 (01-640), 4W0003 (01-650), AS22618 (01-656), 5T8142 (79-21-51, 01-550), 5T8140 (01-580), 5T8143 (01-630), 5T8141 (01-660), 5T8144 (01-710).

- (2) The spareability of the following part has been changed to overhaul use only.

PN. 2A1463 (71-52-43, 04-883)

- (3) The spareability of the following parts has been changed to non-spareable.

PNs. 5W0016 (72-32-00, 01-001), 5R0058 (72-32-35, 01-220), 5A1339 (72-32-37, 01-300), 5A1329 (01-360), AS15777 (73-11-49, 06-200), 5T0039 (74-11-38, 01-335), 5T0042 (01-335), 5T0044 (01-335), 5T0031 (01-735), 5T0046 (01-735), 0F25-005 (79-21-43, 01-165)




(4) Other Publications Affected:

(a) The V2500 Illustrated Parts Catalog will be revised to add or delete the affected parts.

(b) The V2500 Power Plant Illustrated Parts Catalog will be revised to add or delete the affected parts.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
2A1463 (71-52-43)	*	163.00	Wire, 18-8 Steel	2A1463 (04-883)	Not applicable
5T8123 (72-00-50)	1	394.00	Bracket	5T8123 (01-330)	Not applicable
5R0477 (72-00-60)	2	5.86	Washer	5R0477 (01-410)	Not applicable
5R0480 (72-00-60)	4	405.00	Bracket, A/O Al G/Box mount	5R0480 (01-550)	Not applicable
5R0477 (72-00-60)	4	5.86	Washer	5R0477 (01-560)	Not applicable
5R0479 (72-00-60)	2	327.00	Bracket, A/O A3 G/B mount	5R0479 (01-700)	Not applicable
5R0478 (72-00-60)	2	6.99	Washer	5R0478 (01-710)	Not applicable
- (72-32-00)	1	-	Comp, assy LPC/Interm	5W0016 (01-001)	(A)
5R0002 (72-32-00)	10	9.38	Screw, 100 degree flat head	5R0002 (01-310)	Not applicable
5R0003 (72-32-00)	10	13.20	Washer, dimpled	5R0003 (01-315)	Not applicable
5R0012 (72-32-89)	5	2441.00	Lining, A/O acoustic	5R0012 (01-100)	Not applicable
- (72-32-35)	1	-	Holder, brush seal rear	5R0058 (01-220)	(A)
- (72-32-37)	1	-	Tube, A/O NF	5A1339 (01-300)	(A)
- (72-32-37)	1	-	Terminal, A/O Block NF	5A1329 (01-360)	(A)
5W8355 (72-41-34)	1	99.50	Bracket	5W8355 (01-720)	Not applicable
- (74-11-49)	1	-	Wire, thrust	AS15777 (06-200)	(A)
- (74-11-38)	1	-	Bracket	5T0039 (01-335)	(A)
- (74-11-38)	1	-	Bracket	5T0042 (01-335)	(A)
- (74-11-38)	Ref	-	Bracket	5T0044 (01-335)	(A)

V2500-ENG-70-0075




International Aero Engines
INFORMATION BULLETIN

-	1	-	Bracket	5T0031	(A)
(74-11-38)				(01-735)	
-	Ref	-	Bracket	5T0046	(A)
(74-11-38)				(01-735)	
4W0001	1	2.00	Nut, option	4W0001	Not
(74-21-43)				(01-156)	applicable
W0164	16	3.95	Bolt, option	4W0164	Not
(75-22-41)				(01-315)	applicable
5T8266	1	51.60	Pin, locator	5T8266	Not
(79-21-43)				(01-115)	applicable
0F25-009	1	149.00	Plug, drain fuel	0F25-009	Not
(79-21-43)				(01-147)	applicable
0F25-021	1	26.70	Ring, sealing	0F25-021	Not
(79-21-43)				(01-149)	applicable
MS9954-06	1	28.90	Plug, drain oil	MS9954-06	Not
(79-21-43)				(01-157)	applicable
0F25-021	1	26.70	Ring, sealing	0F25-021	Not
(79-21-43)				(01-159)	applicable
-	1	-	Cap, assy	0F25-005	(A)
(79-21-43)				(01-165)	
0F25-014	1	90.60	Ring, sealing	0F25-014	Not
(79-21-43)				(01-171)	applicable
5T8248	1	285.00	Bracket, A/O AL F.C.O.C.	5T8248	Not
(79-21-43)				(01-300)	applicable
5T8249	1	285.00	Bracket, A/O AL	5T8249	Not
(79-21-43)				(01-300)	applicable
4W0002	2	6.65	Nut, self locking dbl	4W0002	Not
(79-21-43)				(01-310)	applicable
5T8080	1	294.00	Bracket, A4	5T8080	Not
(79-21-43)				(01-380)	applicable
5T8222	1	203.00	Bracket, A5	5T8222	Not
(79-21-43)				(01-420)	applicable
4W0003	1	16.50	Nut, self locking dbl	4W0003	Not
(79-21-43)				(01-430)	applicable
AS22622	1	4.28	Bolt, close tol doubl	AS22622	Not
(79-21-43)				(01-435)	applicable
5T8020	1	23.00	Bushing	5T8020	Not
(79-21-43)				(01-440)	applicable
5T8075	1	244.00	Bracket, A2	5T8075	Not
(79-21-43)				(01-505)	applicable
4W0002	1	6.65	Nut, self locking dbl	4W0002	Not
(79-21-43)				(01-515)	applicable
4W0165	1	4.11	Bolt, machine double	4W0165	Not
(79-21-43)				(01-520)	applicable
4W0002	1	6.65	Nut, self locking dbl	4W0002	Not
(79-21-43)				(01-530)	applicable
4W0204	1	7.73	Bolt, machine double	4W0204	Not
(79-21-43)				(01-535)	applicable
5T8078	1	151.00	Bracket, A3	5T8078	Not
(79-21-43)				(01-640)	applicable
4W0003	1	16.50	Nut, self locking dbl	4W0003	Not

Printed in Great Britain

V2500-ENG-70-0075



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

(79-21-43)				(01-650)	applicable
AS22618	1	6.25	Bolt, close tol doubl	AS22618	Not
(79-21-43)				(01-656)	applicable
5T8142	1	387.00	Bracket, A1	5T8142	Not
(79-21-51)				(01-550)	applicable
5T8140	1	436.00	Link, A/O A2	5T8140	Not
(79-21-51)				(01-580)	applicable
5T8143	1	389.00	Bracket, A2	5T8143	Not
(79-21-51)				(01-630)	applicable
5T8141	1	436.00	Link, A/O A3	5T8141	Not
(79-21-51)				(01-660)	applicable
5T8144	1	387.00	Bracket, A3	5T8144	Not
(79-21-51)				(01-710)	applicable

(A) This part is not supplied for future spares.

Not applicable, no part and part availability changed.

*: As required

NOTE: The estimated 1992 unit price shown is provided for planning purposes only and does not constitute a firm quotation.
Contact the IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-70-0075

