

International Aero Engines

Subject : Transmittal of Revision 1 to Service Bulletin No. V2500-ENG-70-0104

Service Bulletin Revision History :

Event	Date
Basic Issue	Oct.05/92
Revision 1	Mar.5/99

Reason for Issuance of Revision :

To revise the engine effectivity

Effect on Past Compliance

None

List of Effective Pages:

Bulletin Page No	Rev No.	Effective Date
R 1	1	Mar.5/99
R 2	1	Mar.5/99
3	Basic	Oct.5/92
4	Basic	Oct.5/92
5	Basic	Oct.5/92

V2500-ENG-70-0104

Transmittal
Page 1 of 1



International Aero Engines INFORMATION BULLETIN

INFORMATION - AIR SYSTEM - INTRODUCE
SPAREPARTS USED IN LPT-ACC REPAIRS

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

75-00-00

Compliance Category Code

8

Internal Reference No.

90VM012
90VM012A
90VM012B



International Aero Engines INFORMATION BULLETIN

INFORMATION - AIR SYSTEM - INTRODUCE SPAREPARTS USED IN LPT-ACC REPAIRS

A. Effectivity

- R (1) Aircraft: Airbus A319
Airbus A320
Boeing Douglas Product Division MD90
- R (2) Engine: V2500-A1 Engines
V2522-A5 Engines
V2524-A5 Engines
V2527-A5 Engines
V2527E-A5 Engines
V2530-A5 Engines
V2533-A5 Engines
V2525-D5 Engines
V2528-D5 Engines
- R
R
R
R
R
R
R
R

B. Reason

Spareparts used in published repairs VRS4253 and VRS4254 are introduced as salable detail parts.

- R This revision extends the use of salable detail parts also for Engine Model V2533 since parts are
R the same for all models.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- R Engineering Change No. 90VM012, 90VM012A and 90VM012B
- IAE Authorization Documents:
- 90VM505 VRS 4253
90VM505A VRS 4254

F. General Information

The Material Information Section of this Bulletin provides the latest information concerning the availability of the spare parts used in repair notes VRS4253 and VRS 4254.

Printed in Great Britain

Oct.5/92

R Revision 1 Mar.5/99

V2500-ENG-70-0104

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Page 2



INFORMATION BULLETIN

G. Material Information

(1) Repair Parts needed for VRS 4253

New Part No. (ATA No.)	Qty.	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
3A1866 (75-24-49)	1	377,00	Tube, A/O, VRS 4253	--- (02-800)	(A)
3A1867 (75-24-49)	1	404,00	Tube, A/O, VRS 4253	--- (02-810)	(A)
3A1868 (75-24-49)	1	410,00	Tube, A/O, VRS 4253	--- (02-820)	(A)
3A1869 (75-24-49)	1	410,00	Tube, A/O, VRS 4253	--- (02-830)	(A)
3A1870 (75-24-49)	1	414,00	Tube, A/O, VRS 4253	--- (02-840)	(A)
3A1871 (75-24-49)	1	390,00	Tube, A/O, VRS 4253	--- (02-850)	(A)
3A1872 (75-24-49)	1	390,00	Tube, A/O, VRS 4253	--- (02-860)	(A)
3A1873 (75-24-49)	1	392,00	Tube, A/O, VRS 4253	--- (02-870)	(A)
3A1858 (75-24-49)	1	377,00	Tube, A/O, VRS 4253	--- (02-880)	(A)
3A1859 (75-24-49)	1	404,00	Tube, A/O, VRS 4253	--- (02-890)	(A)
3A1860 (75-24-49)	1	410,00	Tube, A/O, VRS 4253	--- (02-900)	(A)
3A1861 (75-24-49)	1	410,00	Tube, A/O, VRS 4253	--- (02-910)	(A)
3A1862 (75-24-49)	1	418,00	Tube, A/O, VRS 4253	--- (02-920)	(A)
3A1863 (75-24-49)	1	392,00	Tube, A/O, VRS 4253	--- (02-930)	(A)
3A1864 (75-24-49)	1	390,00	Tube, A/O, VRS 4253	--- (02-940)	(A)
3A1865 (75-24-49)	1	392,00	Tube, A/O, VRS 4253	--- (02-950)	(A)




INFORMATION BULLETIN

G. Material Information (continued)

(2) Repair Parts needed for VRS 4254

New Part No. (ATA No.)	Qty.	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
3A1882 (75-24-49)	1	377,00	Tube, A/O, VRS 4254	--- (03-800)	(A)
3A1884 (75-24-49)	1	410,00	Tube, A/O, VRS 4254	--- (03-810)	(A)
3A1885 (75-24-49)	1	410,00	Tube, A/O, VRS 4254	--- (03-820)	(A)
3A1886 (75-24-49)	1	414,00	Tube, A/O, VRS 4254	--- (03-830)	(A)
3A1887 (75-24-49)	1	387,00	Tube, A/O, VRS 4254	--- (03-840)	(A)
3A1888 (75-24-49)	1	387,00	Tube, A/O, VRS 4254	--- (03-850)	(A)
3A1889 (75-24-49)	1	392,00	Tube, A/O, VRS 4254	--- (03-860)	(A)
3A1874 (75-24-49)	1	377,00	Tube, A/O, VRS 4254	--- (03-870)	(A)
3A1876 (75-24-49)	1	410,00	Tube, A/O, VRS 4254	--- (03-880)	(A)
3A1877 (75-24-49)	1	410,00	Tube, A/O, VRS 4254	--- (03-890)	(A)
3A1878 (75-24-49)	1	458,00	Tube, A/O, VRS 4254	--- (03-900)	(A)
3A1879 (75-24-49)	1	433,00	Tube, A/O, VRS 4254	--- (03-910)	(A)
3A1880 (75-24-49)	1	360,00	Tube, A/O, VRS 4254	--- (03-920)	(A)
3A1881 (75-24-49)	1	392,00	Tube, A/O, VRS 4254	--- (03-930)	(A)
3A1875 (75-24-49)	1	837,00	Tube, A/O, VRS 4254	--- (03-940)	(A)
3A1883 (75-24-49)	1	837,00	Tube, A/O, VRS 4254	--- (03-950)	(A)



V2500 Propulsion System - Engine General

INFORMATION BULLETIN

H. Instruction/Disposition Code Statement

(A) New part is available for sale

NOTE: The estimated 1993 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain