

STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - INTRODUCE VARIOUS REVISED MATERIAL
EXTERNAL BRACKETS - CATEGORY CODE 7 - MOD.ENG-70-0158

1. Planning Information

A. Effectivity

(1) Aircraft : Airbus A320

(2) Engine : V2500-A1

B. Reason

To announce the introduction or revised material harness and pipe support brackets.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transactions shown under the MATERIAL INFORMATION portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) Internal Reference No.

EC91VR025


F. General Information

The Material Information portion of this Bulletin provides the latest information concerning the availability of new harness and pipe support brackets.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
6A4664 (71-51-41)	1		Bracket	5W8383 (05-820)	(A)(B)(S1)

V2500-ENG-70-0158



International Aero Engines
INFORMATION BULLETIN

6A4665 (71-51-41)	1		Bracket	5W8337 (05-850)	(A)(B)(S1)
6A4666 (71-51-41)	4		Bracket	5W8316 (05-910)	(A)(B)(S1)
6A4667 (71-51-41)	4	32.90	Bracket	5W8315 (05-920)	(A)(B)(S1)
6A4688 (71-51-41)	1		Bracket, Assy of	5A9186 (05-940)	(A)(B)(S1)
6A4668 (71-51-41)	2	39.40	Bracket	5W8382 (05-990)	(A)(B)(S1)
6A4669 (71-51-49)	1	75.90	Bracket	5W0089 (01-390)	(A)(B)(S1)
6A4670 (72-41-00)	1	240.00	Bracket, Assy of	5W1999 (03-550)	(A)(B)(S1)
6A4671 (72-41-00)	1	63.90	Bracket	5W8357 (03-790)	(A)(B)(S1)
6A4673 (72-60-00)	1	139.00	Bracket	5W8361 (01-122)	(A)(B)(S1)
6A4674 (73-11-47)	1		Bracket	5W2160 (01-070)	(A)(B)(S1)
6A4711 (73-22-34)	1	39.40	Bracket	5W8512 (01-520)	(A)(B)(S1)
6A4675 (73-22-49)	1	101.00	Bracket	5W8358 (03-470)	(A)(B)(S1)
6A4676 (73-22-49)	2	39.70	Bracket	5W8246 (08-060)	(A)(B)(S1)
6A4677 (73-22-49)	2	45.06	Bracket, Clipping	5W8261 (08-070)	(A)(B)(S1)
6A4678 (74-11-38)	1	24.20	Bracket	5W8267 (01-590)	(A)(B)(S1)
6A4679 (74-11-38)	1	120.00	Bracket	5W8380 (01-740)	(A)(B)(S1)
6A4681 (75-31-42)	1		Bracket	5W8269 (01-080)	(A)(B)(S1)

Printed in Great Britain

V2500-ENG-70-0158



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

6A4672 (75-32-41)	1	154.00	Bracket, Assy of	5W8366 (01-070)	(A)(B)(S1)
6A4680 (75-32-51)	2	39.40	Bracket	5W8314 (01-150)	(A)(B)(S1)
6A4689 (79-11-41)	1		Bracket	5W8391 (01-101)	(A)(B)(S1)
6A4682 (79-21-42)	1	46.10	Bracket	5W8327 (01-084)	(A)(B)(S1)
6A4683 (79-21-42)	1	111.00	Bracket	5W8377 (01-088)	(A)(B)(S1)
6A4684 (79-21-42)	1	259.00	Bracket, Assy of	5W8537 (01-090)	(A)(B)(S1)
6A4685 (79-21-42)	1	63.40	Bracket	5W8257 (01-350)	(A)(B)(S1)
6A4686 (79-21-49)	2	217.00	Bracket	5W8249 (04-070)	(A)(B)(S1)
6A4687 (79-21-49)	1	39.40	Bracket	5W8447 (06-070)	(A)(B)(S1)
6A4711 (79-22-49)	1	39.40	Bracket	5W8512 (04-470)	(A)(B)(S1)
6A4712 (79-22-49)	1	89.90	Bracket	5W8248 (10-470)	(A)(B)(S1)

H. Supply Status Code Statements

(A) New Part is currently available.

(B) Old Part will no longer be available.

(S1) Old and new parts are freely and fully interchangeable, both physically and functionally.

NOTE: The estimated 1994 unit prices are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-70-0158

Jan.14/94

Page 3

