



International Aero Engines

Subject : Transmittal of Revision 1 to Service Bulletin No. V2500-ENG-70-0186

Service Bulletin Revision History :

Event	Date
Basic Issue	Oct.05/92
Revision 1	Mar.5/99

Reason for Issuance of Revision :

To revise the engine effectivity

Effect on Past Compliance

None

List of Effective Pages:

Bulletin Page No	Rev No.	Effective Date
R 1	1	Mar.5/99
R 2	1	Mar.5/99
R 3	1	Mar.5/99

V2500-ENG-70-0186

Transmittal
Page 1 of 1



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP TURBINE
PROVIDE ACC CONNECTOR REPAIR PARTS

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

75-00-00

Compliance Category Code

8

Internal Reference No.

92VM002
92VM002A

Oct.5/92

R Revision 1 Mar.5/99

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

V2500-ENG-70-0186

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP TURBINE PROVIDE ACC CONNECTOR REPAIR PARTS

A. Effectivity

- R (1) Aircraft: Airbus A319
R Airbus A320
R Boeing Douglas Product Division MD90
- R (2) Engine: V2500-A1 Engines
R V2522-A5 Engines
R V2524-A5 Engines
R V2527-A5 Engines
R V2527E-A5 Engines
R V2530-A5 Engines
R V2533-A5 Engines
R V2525-D5 Engines
R V2528-D5 Engines

B. Reason

To announce the availability of salable detail parts for ACC clamp retaining rivet replacement in accordance with VRS 4252.

- R This revision extends the use of salable detail parts also for Engine Model V2533 since parts are
R the same for all models.

C. Compliance

Category Code 8

Based on experience with the prior configuration

D. Approval

The part number transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- R Engineering Change No. 92VM002 and 92VM002A
IAE Authorization Documents:
91VM503B VRS 4252

F. General Information

The Material Information Section of this Bulletin provides the latest information concerning the availability of the ACC clamp retaining rivets.

Printed in Great Britain

Oct.5/92

R Revision 1 Mar.5/99

V2500-ENG-70-0186

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Page 2



International Aero Engines INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty.	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
AN123184 (75-24-49)	ref	2.12	Rived, Solid Universal Head	--- (01-401)	(A)
NAS1398C4-1 (75-24-49)	ref	---	Rivet, blind	--- (01-401)	(A)

H. Instruction/Disposition Code Statement

(A) New part is available for sale

NOTE: The estimated 1992 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.