



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - PROVIDE ADDITIONAL
CLASSES OF HPC ROTOR ADJUSTING WASHERS - CATEGORY CODE 8 - MOD.ENG-70-0240

1. Planning Information

A. Effectivity

- (1) Aircraft : Airbus A320
- (2) Engine : V2500-A1

B. Reason

The new adjusting washers have been introduced in addition to the current series of washers to make the HPC Rotor Center setting easier.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transaction shown under the Material Information in paragraph has been shown to comply with the applicable Federal Aviation Regulation and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.
92VJ108

F. General Information

- (1) The following four additional HPC Rotor Center adjusting washers have been introduced:
 - (a) 5A0890, Adjusting washer 0.202 in (5,13 mm) thickness
 - (b) 5A0891, Adjusting washer 0.212 in (5,38 mm) thickness
 - (c) 5A1500, Adjusting washer 0.223 in (5,68 mm) thickness
 - (d) 5A1501, Adjusting washer 0.231 in (5,88 mm) thickness
- (2) Other publications affected:
 - (a) V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-26, will be revised to show the new part numbers.

V2500-ENG-70-0240



International Aero Engines
INFORMATION BULLETIN

(b) V2500 Engine Manual, 72-32-20, Disassembly, Assembly, will be revised to show the new part number.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5A0890 (72-32-26)	1	141.00	.Washer, Adjusting HPC	--- (01-511)	(A)
5A0891 (72-32-26)	1	141.00	.Washer, Adjusting HPC	--- (01-512)	(A)
5A1500 (72-32-26)	1	129.00	.Washer, Adjusting HPC	--- (01-513)	(A)
5A1501 (72-32-26)	1	129.00	.Washer, Adjusting HPC	--- (01-514)	(A)

H. Instruction/Disposition Code Statement:

(A) New part is currently available.

NOTE: The estimated 1993 unit prices shown is provided for planning purposes only and does not constitute a firm quotation. Contact the IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0240