

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10
 EAST HARTFORD, CT 06108, USA.
 TELEPHONE: 860 565 5515
 FAX: 860 565 0600

DATE **Jul.14/00**

P.O. BOX 31, DERBY
 TELEGRAMS - 'ROYCAR' DERBY
 TELEX - 37645
 TELEPHONE - DERBY 242424

Printed in Great Britain

V2500-A1 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits Revision 1 to Service Bulletin EV2500-70-0242

Document History

Service Bulletin Revision Status
 Initial Issue Apr.15/93

Supplement Revision Status

Bulletin Revision 1

Remove
 All pages of the
 Service Bulletin

Incorporate
 Page 1 and 2 of the
 Service Bulletin

Reason for change
 To revise Section 2.
 Material Information to
 include Vendor Part Nos.

V2500-ENG-70-0242

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED

If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England

© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 1 are as follows:

<u>Page</u>		<u>Revision Number</u>	<u>Revision Date</u>
	Bulletin		
R	1	1	Jul.14/00
R	2	1	Jul.14/00

Printed in Great Britain



STANDARD PRACTICES - ENGINE -OIL - PROVIDE A NEW NO.4 BEARING PRESSURE TRANSDUCER
WITH REVISED OUTPUT CHARACTERISTICS

1. Planning Information

A. Effectivity

(1) Airbus A320

V2500-A1 Engines prior to Serial No. V0362

B. Reason

To provide a new No.4 Bearing Pressure Transducer which has the revised characteristics for the output voltage.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transaction shown under the MATERIAL INFORMATION portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and is FAA approved for the engine model listed.

E. Reference

Internal Reference No. EC92VJ047

F. General Information

- (1) The material information portion of this Bulletin provides the latest information concerning the availability of the new No.4 Bearing Pressure Transducer.
- (2) Other Publications Affected:
 - (a) V2500 Engine Illustrated Parts Catalog, Chapter/Section 79-33-16 will be revised to show the new part number.
 - (b) V2500 Powerplant Illustrated Parts Catalog, Chapter/Section 79-33-16 will be revised to show the new part number.



2. Material Information

A. Parts affected by this Bulletin:

V2500-A1 Engines

79-33-16

	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
R	01100	41SG272-5 (5L0049)	1	Transducer, Pressure No.4	-	41SG272-3 (5L0026)	(A)(B) (1)

B. Instructions disposition codes

(A) New part will be available in November 1993

(B) Old part will no longer be available for sale

(1) Old and new parts are freely and fully interchangeable, both physically and functionally

NOTE: The prices (if shown) are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales department for information concerning firm prices.

3. Accomplishment Instructions

None