Date: October 19, 1999

Subject: Transmittal of Revision 1 to Service Bulletin Number V2500-ENG-70-0315

Service Bulletin Revision History:

Event Date

Basic Issue Sep. 15, 1995 Revision 1 Oct. 19, 1999

Reasons for issuance of Revision:

- (1) To amend the effectivity.
- (2) To amend Paragraph F.(1).
- (3) To amend the part numbers in Paragraph G.

Effect on Past Compliance:

None.

List of Effective Pages:

Page No. Rev. No. Date

1 thru 3 1 Oct. 19/99

V2500-ENG-70-0315

Page 1 of 1 Transmittal



INFORMATION - ENGINE – TO ANNOUNCE THE AVAILABILITY OF A NEW BRACKET AT CLIPPING POINT CP1200.

MODEL APPLICATION

R R R R

V2522-A5 V2524-A5 V2527-A5 V2527E-A5 V2527M-A5 V2530-A5

BULLETIN INDEX LOCATOR

71-00-00

COMPLIANCE CATEGORY CODE

INTERNAL REFERENCE NO. SM 93VN089

September 15, 1995 Revision 1 - October 19, 1999 V2500-ENG-70-0315
Page 1 of 3

INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF A NEW BRACKET AT CLIPPING POINT CP1200

A. **EFFECTIVITY**

(1) AIRCRAFT	Γ:

- (a) Airbus A319 R
 - (a) Airbus A320
 - Airbus A321 (b)
 - (2) ENGINE:
- R V2522-A5 (a) R V2524-A5 (b) R V2527-A5 (c) R V2527E-A5 (d) R V2527M-A5 (e)
 - V2530-A5 (f)
 - B. **REASON**

R

R

To announce the availability of new bracket at clipping point CP1200 to improve routing of harness.

C. **COMPLIANCE**

Caterogy code 7.

Accomplish when the supply of superseded pards has been depleted.

D. APPROVAL

The change in definition subject of the Service Bulletin has been covered by an aircraft modification approved by the DGAC (Direction Generale de l'Aviation Civile - France).

E. REFERENCES

(1) IAE Engineering Change No. 93VN089.

F. GENERAL INFORMATION

- R (1) New Bracket introduced to improve routing of the Fancase Electrical Harness.
 - The Material Information portion of this bulletin provides the latest information concerning the (2)availability of the new bracket.
 - (3) Other publications affected.

September 15, 1995 Revision 1 - October 19, 1999 V2500-ENG-70-0315

Page 2 of 3

- (a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA locations.
- (b) The V2500 Power Plant Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA Locations.

G. MATERIAL INFORMATION

Applicability: For each V2500 Engine to incorporate this Bulletin.

New		Est'd		Old	
Part No		Unit		Part No	Supply
(ATA No)	<u>Qty</u>	Price (\$)	Keyword	(IPC No)	Status
745-5997-501 (71-51-50)	1	\$46.00	Bracket	745-5994-503 (01-920)	(A)(1)

Instructions/Dispositions Code Statements.

R

- (A) New parts are currently available.
- Old part number may be used as a replacement where old part number was installed. New part number is acceptable replacement for the old or new part number.
- R NOTE: The estimated 1999 Unit Price shown is provided for planning purposes only and do not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm prices.

September 15, 1995 Revision 1 - October 19, 1999 V2500-ENG-70-0315
Page 3 of 3

