



STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
AVAILABILITY OF NEW MATERIAL ADJUSTING WASHERS - CATEGORY CODE 7 - MOD.ENG-70-0390

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A320
(b) Airbus A321
(c) McDonnell Douglas MD-90
- (2) Engine: (a) V2500-A1 Engines
(b) V2527-A5 Engines
(c) V2530-A5 Engines
(d) V2525-D5 Engines
(e) V2528-D5 Engines

B. Reason

To provide the new material Adjusting Washers.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Models listed.

E. References

- (1) Internal Reference No.

92VJ141

F. General Information

- (1) The Material Information portion of this Bulletin provides the latest information concerning the availability of the new Adjusting Washers.
- (2) V2500 Engine Illustrated Parts Catalogs (S-V2500-1IA, S-V2500-2IA and S-V2500-3IA), Chapter/Section 72-32-26 will be revised.

V2500-ENG-70-0390



International Aero Engines
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status

(1) For V2500-A1 engines					
5A1539 (72-32-26)	1	129.00	.Washer, Adjusting PT0 THK 0.177(4,5)	5A1001 (01-430)	(A)(B)(S1)
5A1540 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.179(4,55)	5A1002 (01-431)	(A)(B)(S1)
5A1541 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.181(4,6)	5A1003 (01-432)	(A)(B)(S1)
5A1542 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.183(4,65)	5A1004 (01-433)	(A)(B)(S1)
5A1543 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.185(4,7)	5A1005 (01-434)	(A)(B)(S1)
5A1544 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.187(4,75)	5A1006 (01-435)	(A)(B)(S1)
5A1545 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.189(4,8)	5A1007 (01-436)	(A)(B)(S1)
5A1546 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.191(4,85)	5A1008 (01-437)	(A)(B)(S1)
5A1547 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.193(4,9)	5A1009 (01-438)	(A)(B)(S1)
5A1548 (72-32-26)	Ref		.Washer, Adjusting PT0 THK 0.195(4,95)	5A1010 (01-439)	(A)(B)(S1)

Printed in Great Britain

V2500-ENG-70-0390



International Aero Engines
INFORMATION BULLETIN

Printed in Great Britain

5A1549 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.197(5,0)	5A1011 (01-440)	(A)(B)(S1)
5A1535 (72-32-26)		.Washer, Adjusting PT0 THK 0.169(4,3)	5A1032 (01-451)	(A)(B)(S1)
5A1536 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.171(4,35)	5A1033 (01-452)	(A)(B)(S1)
5A1537 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.173(4,4)	5A1034 (01-453)	(A)(B)(S1)
5A1538 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.175(4,45)	5A1035 (01-454)	(A)(B)(S1)


(2) For V2527-A5/V2530-A5/V2525-D5/V2528-D5 engines

5A1554 (72-32-26)	1	.Washer, Adjusting PT0 THK 0.177(4,5)	5A0873 (01-430)	(A)(B)(S1)
5A1555 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.179(4,55)	5A0874 (01-431)	(A)(B)(S1)
5A1556 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.181(4,6)	5A0875 (01-432)	(A)(B)(S1)
5A1557 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.183(4,65)	5A0876 (01-433)	(A)(B)(S1)
5A1558 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.185(4,7)	5A0877 (01-434)	(A)(B)(S1)
5A1559 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.187(4,75)	5A0878 (01-435)	(A)(B)(S1)
5A1560 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.189(4,8)	5A0879 (01-436)	(A)(B)(S1)

V2500-ENG-70-0390

Jul. 15/95

Page 3




International Aero Engines
INFORMATION BULLETIN

5A1561 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.191(4,85)	5A0880 (01-437)	(A)(B)(S1)
5A1562 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.193(4,9)	5A0881 (01-438)	(A)(B)(S1)
5A1563 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.195(4,95)	5A0882 (01-439)	(A)(B)(S1)
5A1564 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.197(5,0)	5A0883 (01-440)	(A)(B)(S1)
5A1565 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.199(5,05)	5A0884 (01-441)	(A)(B)(S1)
5A1566 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.201(5,1)	5A0885 (01-442)	(A)(B)(S1)
5A1567 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.203(5,15)	5A0886 (01-443)	(A)(B)(S1)
5A1568 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.205(5,2)	5A0887 (01-444)	(A)(B)(S1)
5A1550 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.16(4,3)	5A0869 (04-451)	(A)(B)(S1)
5A1551 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.171(4,35)	5A0870 (01-452)	(A)(B)(S1)
5A1552 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.173(4,4)	5A0871 (01-453)	(A)(B)(S1)
5A1553 (72-32-26)	Ref	.Washer, Adjusting PT0 THK 0.175(4,45)	5A0872 (01-454)	(A)(B)(S1)

Printed in Great Britain

V2500-ENG-70-0390



H. Supply Status Code Statements:

- (A) New part is currently available.
- (B) Old part is no longer available.

(S1) Old and New parts are freely and fully interchangeable, both physically and functionally.

NOTE: The estimated 1995 unit prices shown are provided for planning purposes only and do not constitute the firm quotations. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

