

International Aero Engines INFORMATION BULLETIN

Mar. 12/99

Subject: Transmittal of Revision 3 to Service Bulletin Number
V2500-ENG-70-0427.

Service Bulletin Revision History:

Event	Date
Basic Issue	Jan. 29/96
Revision 1	Oct. 25/96
Revision 2	Sep. 04/98
Revision 3	Mar. 12/99

Reason for Issuance of Revision:

(1) To amend the internal reference No. and paragraph E in line with EC 98VJ001.

Effect on Past Compliance:

None

List of Effective Pages:

Bulletin Page No.	Rev. No.	Effective Date
R 1 to 2	3	Mar. 12/99
R 3	2	Sep. 04/98

V2500-ENG-70-0427

Transmittal
Page 1 of 1



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
NEW SEAL ASSEMBLY FOR THE BIFURCATION BOX

MODEL APPLICATION

V2525 - D5
V2528 - D5

BULLETIN INDEX LOCATOR

72-38-00


Compliance Category Code

7

Internal Reference No.

94VJ073
92VJ055-03
98VJ001

R



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
NEW SEAL ASSEMBLY FOR THE BIFURCATION BOX

A. Effectivity

(1) Aircraft

R Boeing MD-90

(2) Engine

(a) V2525 - D5 Engines

(b) V2528 - D5 Engines

B. Reason

To announce the availability of the new Seal Assembly for the Bifurcation Box with improved repairability.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The part number transaction given in the Material Information section of this Bulletin comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

E. Reference

R IAE Engineering Change No. 94VJ073, 98VJ001 and Engineering Change Memo No. 92VJ055-03.

F. General Information

(1) The Material Information section of this Bulletin gives the latest information about the availability of the new Seal Assembly for the Bifurcation Box.

(2) Other Publications Affected:

V2500 Engine Illustrated Parts Catalog (S-V2500-3IA), Chapter/Section 72-38-27

Printed in Great Britain


Jan. 29/96

R Revision 3 Mar. 12/98

V2500-ENG-70-0427

Not subject to the EAR per 15 C.F.R. Chapter 1, Part 734.3(b)(3).

Page 2



International Aero Engines INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
5T0136 (72-38-27)	1		Seal, Assy Bifurcation	- (01-205)	(A)
5T0137 (72-38-27)	1		Retainer, Seal	- (01-210)	(A)

R NOTE: The unit prices, if shown, are an estimate and they are given for the
R purpose of planning only. For information about actual prices, refer
R to the IAE Price Catalog or contact IAE's Spare Parts Sales
R Department.

H. Supply Status Code Statements:

(A) New parts are currently available for sale.

Printed in Great Britain