

STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE
AVAILABILITY OF REPAIR PARTS TO SUPPORT THE REPAIR OF FAN FRAME ASSEMBLIES - CATEGORY
CODE NA - MOD.ENG-70-0482

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) McDonnell Douglas MD-90
- (2) Engine: (a) V2525-D5 Engines
(b) V2528-D5 Engines

B. Reason

To announce the availability of the newly released Repair Parts by changing the spareability code from not spareable to potential spare for overhaul uses only.

C. Compliance

For information only.

D. Approval

The part number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- (1) Internal Reference No.
ECMD5723203-03


F. General Information

- (1) A New Repair Scheme will be introduced into the V2500 Engine Manual which requires the special Repair Parts for its accomplishment.

ATA No. -----	Repair Scheme -----	Title -----
72-32-03	VRS1194	Intermediate structure fan frame - Replace the insert

- (2) The spareability coding for the inserts, part number AGS3732 item number 01-925, changes from not spareable to potential spare for overhaul uses only.

V2500-ENG-70-0482



International Aero Engines
INFORMATION BULLETIN

- (3) The Material Information portion of this Bulletin provides the latest information concerning the availability of the special Repair Parts required.
- (4) V2500 Engine Illustrated Parts Catalogs (S-V2500-3IA), Chapter/Section 72-32-03 will be revised to incorporate the new parts.

G. Material Information

The following special Repair Parts are required to accomplish the Repair Scheme VRS1194.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
AGS3732 (72-32-03)	3		..Insert,Screw Thread	- (01-925)	(A)

NOTE: The unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

H. Supply Status Code Statements:

- (A) New part is currently available.

Printed in Great Britain

V2500-ENG-70-0482