

STANDARD PRACTICES - ENGINE - INFORMATION - ENGINE - LP TURBINE ROTOR AND STATOR
ASSEMBLY - INTRODUCE NEW SEAL STRIPS AT THE LP TURBINE - DIFFUSOR SEGMENTS - CATEGORY
CODE 7 - MOD.ENG-70-0504

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A320
Airbus A321
McDonnell Douglas MD90
- (2) Engine: V2500-A1 Engines
V2522-A5 Engines
V2524-A5 Engines
V2527-A5 Engines
V2530-A5 Engines
V2533-A5 Engines
V2525-D5 Engines
V2528-D5 Engines

B. Reason

To announce the availability of new LP Turbine feather seals with revised material.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The partnumber transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) Internal Reference No.


95VM006

95VM006A

F. General Information

- (1) The Material Information Section of this bulletin provides the latest information concerning the availability of the seal strips.

V2500-ENG-70-0504



International Aero Engines
INFORMATION BULLETIN

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
3A2427 (72-50-24)	12		Seal,strip	3A0112 (01-070)	(A) (B) (1)
3A2426 (72-50-25)	16		Seal,strip	3A0093 (01-290)	(A) (B) (1)
3A2425 (72-50-25)	16		Seal,strip	3A1794 (01-290)	(A) (B) (1)

H. Instruction/Disposition Code Statement

(A) New part is available for sale.

(B) Supply of old part will be discontinued

(1) Old and new part freely and fully interchangeable

NOTE: The estimated 1996 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

Printed in Great Britain

V2500-ENG-70-0504