



International Aero Engines

Subject : Transmittal of Revision 1 to Service Bulletin No. V2500-ENG-70-0519

Service Bulletin Revision History :

Event	Date
Basic Issue	Sep.22/97
Revision 1	Jul.19/99

Reason for Issuance of Revision :

Model usage has been clarified, Engine S/N and prices have been added

Effect on Past Compliance

None

List of Effective Pages:

Bulletin Page No	Rev No.	Effective Date
R 1	1	Jul.19/99
R 2	1	Jul.19/99
R 3	1	Jul.19/99

V2500-ENG-70-0519

Transmittal
Page 1 of 1



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF A NEW LP TURBINE
CASE MADE OUT OF ONE FORGING PIECE

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2530-A5
V2533-A5
V2525-D5
V2528-D5

BULLETIN INDEX LOCATOR

72-50-00

Compliance Category Code


7

Internal Reference No.

96VM015
96VM015A

Sep.22/97
Revision 1 Jul.19/99

V2500-ENG-70-0519
Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - TO ANNOUNCE THE AVAILABILITY OF
A NEW LP TURBINE CASE MADE OUT OF ONE FORGING PIECE

A. Effectivity

- (1) Aircraft: Airbus A319
Airbus A320
Airbus A321
Boeing Douglas Product Division MD90
- (2) Engine: V2522-A5 Engines prior Engine S/N V0362
V2524-A5 Engines prior Engine S/N V10290
V2527-A5 Engines prior Engine S/N V10290
V2527E-A5 Engines prior Engine S/N V10290
V2530-A5 Engines prior Engine S/N V10290
V2533-A5 Engines prior Engine S/N V10290
V2525-D5 Engines prior Engine S/N V20290
V2528-D5 Engines prior Engine S/N V20290

B. Reason

- To announce the availability of a new LP turbine case made out of one forging piece.
The revision 1 of this Service Bulletin introduces a one forging piece LP turbine case for V2500 A1 engines as a spare part.

C. Compliance

Category Code 7

Accomplish when supply of superseded parts has been depleted.

D. Approval

The partnumber transaction shown under the Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- Engineering Change No. 96VM015
96VM015A

F. General Information

The Material Information Section of this Bulletin provides the latest information concerning the affected parts.

Printed in Great Britain

Sep.22/97

R Revision 1 Jul.19/99

V2500-ENG-70-0519

Page 2



International Aero Engines INFORMATION BULLETIN

G. Material Information

	New Part No. (ATA No.)	Qty.	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
R	Applicability for A5 and D5 engines affected by this Service Bulletin:					
R	3A2447 (72-50-21)	1	197,780.00	Case LP Turbine	3A2183 (01-010)	(A) (B) (1)
R	Applicability for A1 engines affected by this Service Bulletin:					
R	3A2533 (72-50-21)	1	197,780.00	Case LP Turbine	3A2265 (01-010)	(A) (B) (1)
R						

H. Instruction/Disposition Code Statement

- (A) New part is currently available for sale
- (B) Old part will continue to be supplied until the existing stock is exhausted
- (1) Old and new parts are fully interchangeable

R **NOTE:** The estimated 1999 unit prices shown are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact IAE's Spare Parts Sales Department for information concerning firm prices.

