400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600

DATE: Jan.22/04

P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

V2500-A5/D5 PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits Revision 2 to Service Bulletin EV2500-70-0525 and Revision 2 to the Supplement

Document History

Service Bulletin Revision Status Supplement Revision Status
Initial Issue Aug.31/98 Initial Issue Aug.31/98
Revision 1 Nov.18/03 Revision 1 Nov.18/03

Bulletin Revision 2

Remove Incorporate Reason for change

All pages of the Pages 1 to 3 of the To add Disposition Code (C) Service Bulletin Service Bulletin to Material Information

Supplement Revision 2

Remove Incorporate Reason for change

All pages Page 1 To add Disposition Code (C) to Material Information

V2500-ENG-70-0525

Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 2 to the Bulletin and Revision 2 to the Supplement are as follows:

<u>Page</u>		Revision Number	Revision Date		
Bu	lletin				
R	1	2	Jan.22/04		
R	2	2	Jan.22/04		
R	3	2	Jan.22/04		
Supplement					
R	1	2	Jan.22/04		



<u>INFORMATION - LP TURBINE ROTOR AND STATOR ASSEMBLY - TO ANNOUNCE THE AVAILABILITY OF</u> <u>A NEW DIFFUSOR OUTER SEGMENT</u>

1. Planning Information

A. Effectivity

(1) Aircraft

Airbus A321

Airbus A320

Airbus A319

Boeing Douglas Product Division MD90

(2) Engine

V2522-A5 Engines prior to Serial No. V10449

V2524-A5 Engines prior to Serial No. V10449

V2527-A5 Engines prior to Serial No. V10449

V2527E-A5 Engines prior to Serial No. V10449

V2530-A5 Engines prior to Serial No. V10449

V2533-A5 Engines prior to Serial No. V10449

V2525-D5 Engines prior to Serial No. V20252

V2528-D5 Engines prior to Serial No. V20252

B. Reason

To announce the availability of new outer diffusor segments with modified leading edge contour.

C. <u>Compliance</u>

Category Code 7

Accomplish when supply of superseded parts has been depleted.

Aug.31/98 R Jan.22/04 V2500-ENG-70-0525

D. Approval

The part number changes and/or part modification described in Section 2 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA- APPROVED for the Engine Models listed.

E. General Information

The Material Information Section of this Service Bulletin provides the latest information concerning the affected parts.

F. References

R

- (1) Engineering Change No. 97VM010, 97VM010-01 and 97VM010-02.
- (2) ATA Locator 72-50-00.

2. Material Information

A. The kit required consists of the following parts:

None.

B. New production parts:

Part No.	Qty	Unit Price
3A2482	16	Price on request
3A2485	16	Price on request

C. Parts affected by this Bulletin:

72-50-25

	FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
R	01-200	3A2482	16	Diffusor, A/O, segment outer	3A1791	(A)(C)(S1)
	01-290	3A2485	16	Seal, strip	3A2425	(A)(B)(S1)

D. <u>Instructions disposition codes:</u>

- (A) New part is currently available for sale
- (B) Old part will continue to be supplied
- R (C) Old part will continue to be supplied until the existing stock is exhausted
 - (S1) Old and new parts are not interchangeable but a complete item number location group or set of components may however be freely interchanged

3. Accomplishment Instructions

None.

Aug.31/98 V2500-ENG-70-0



<u>INFORMATION - LP TURBINE ROTOR AND STATOR ASSEMBLY - TO ANNOUNCE THE AVAILABILITY OF</u> <u>A NEW DIFFUSOR OUTER SEGMENT</u>

SUPPLEMENT - PRICES AND AVAILABILITY

The prices if shown are for estimating purposes only and as such are given in good faith, without commercial liability for advanced planning purposes only. Refer to IAE Spares and/or current price catalogue for current prices.

1. Modification Kit:

Not applicable.

2. New Production Parts:

Part No.	Desc.	Unit Price US Dollars
3A2482	Diffuser, A/O, segment outer	Price on request
3A2485	Seal, strip	Price on request

Aug.31/98
R Jan.22/04

V2500-ENG-70-0525
Supplement Page 1 of 1

