



STANDARD PRACTICES - ENGINE - INFORMATION - ANNOUNCEMENT OF AVAILABILITY OF ALTERNATIVE
AIR MOISTURE TRAPS - CATEGORY CODE 7 - MOD.ENG-70-0571

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A319
(b) Airbus A320
(c) Airbus A321
- (2) Engines: (a) V2500-A1 Engines prior to Serial No.V0362
(b) V2522-A5 Engines prior to Serial No.V10151
(c) V2524-A5 Engines prior to Serial No.V10151
(d) V2527-A5 Engines prior to Serial No.V10151
(e) V2530-A5 Engines prior to Serial No.V10151

B. Reason

To announce the availability of alternative moisture traps for air tube assemblies.

C. Compliance

Category Code 7

This Service Bulletin can be done when there are no initial parts remaining.

D. Approval

The part number transactions are given in "Material Information" section of this Service Bulletin. They obey the applicable Federal Aviation Regulations are are FAA-APPROVED for the engine model listed.

E. References

- (1) Internal Reference No.

EC94VR048

F. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.

V2500-ENG-70-0571



G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
UP11197 (73-22-49)	1	246.00	Trap, moisture - assy of	- (01-226)	(A)(B)(F)
UP11197 (73-22-49)	1		Trap, moisture - assy of	- (02-618)	(A)(B)(E)
UP11198 (73-22-49)	1	220.00	Trap, moisture - assy of	- (08-418)	(A)(C)(G)

NOTE: The 1997 unit prices, if shown, are an estimate and they are given for the purpose of planning only. For information about actual prices, refer to the IAE Price Catalog or contact IAE's Spare Parts Sales Department.

H. Instructions Disposition Codes:

- (A) Additional
- (B) Alternative to 5A9373
- (C) Alternative to 5A9376
- (E) New part will not be made available as a spare for replenishment purposes, part of assembly at chapter 73-22-49 fig/item 02-500
- (F) New part will not be made available as a spare for replenishment purposes, part of assembly at chapter 73-22-49 fig/item 01-100
- (G) New part will not be made available as a spare for replenishment purposes, part of assembly at chapter 73-22-49 fig/item 08-300