



STANDARD PRACTICES – ENGINE – INFORMATION – TO ANNOUNCE THE TRANSFER OF THE MANUFACTURE
OF THE LP/HP FUEL PUMP FROM TEIJIN SEIKI COMPANY LIMITED TO SUNDSTRAND AEROSPACE –
CATEGORY CODE N/A – MOD.ENG-70-0716

1. Planning Information

A. Effectivity

- (1) Aircraft:
- (a) Airbus A319
 - (b) Airbus A320
 - (c) Airbus A321
 - (d) Boeing-Douglas Product Division MD-90
- (2) Engines:
- (a) V2522-A5 Engines prior to Serial No. V10586
 - (b) V2524-A5 Engines prior to Serial No. V10586
 - (c) V2527-A5 Engines prior to Serial No. V10586
 - (d) V2527E-A5 Engines prior to Serial No. V10586
 - (e) V2530-A5 Engines prior to Serial No. V10586
 - (f) V2533-A5 Engines prior to Serial No. V10586
 - (g) V2525-D5 Engines prior to Serial No. V20181
 - (h) V2528-D5 Engines prior to Serial No. V20181

B. Concurrent requirements

None

C. Reason

To announce the transfer of the manufacture of the LP/HP Fuel Pump from Teijin Seiki Company Limited to Sundstrand Aerospace.

D. Compliance

For Information Only.

E. Approval

The part number transactions are given in the "Material Information" section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model Listed.

F. References

- (1) Internal Reference No.

EC99VI001

- (2) Other Reference No.

IAE Engineering Change Number 99VI001.

V2500-ENG-70-0716



International Aero Engines
INFORMATION BULLETIN

G. General Information

- (1) The Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.

H. Other Publications Affected


- (1) Illustrated Parts Catalogue (IPC), Chapter/Section 73-12-41

Printed in Great Britain

V2500-ENG-70-0716

Apr. 10/99

Page 2



International Aero Engines
INFORMATION BULLETIN

2. Material Information

A. Kits necessary for this Service Bulletin:

None.

B. Parts affected by this Service Bulletin:

NEW PART No. (ATA No.)	QTY	EST'D UNIT PRICE (\$)	PART TITLE	OLD PART No. (IPC No.)	INSTR DISP
------------------------------	-----	-----------------------------	------------	------------------------------	---------------

The type of equipment affected by this modification is listed below for information only:-

A5 Models

5009913E (73-12-41)	1	Pump, Fuel LP/HP (V99167)	50009913E (01.100)	(A)
------------------------	---	------------------------------	-----------------------	-----

D5 Models

5010216E (73-12-41)	1	Pump, Fuel LP/HP (V99167)	5010216E (01.100)	(A)
------------------------	---	------------------------------	----------------------	-----

C. Instruction Disposition Code

(1)(A) Vendor cage code has changed from 'VS4980' for Teijin Seiki Company Limited to 'V99167' for Sundstrand Aerospace.

V2500-ENG-70-0716

Apr.10/99

Page 3

