

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10
 EAST HARTFORD, CT 06108, USA.
 TELEPHONE: 860 565 5515
 FAX: 860 565 0600

P.O. BOX 31, DERBY
 TELEGRAMS - 'ROYCAR' DERBY
 TELEX - 37645
 TELEPHONE - DERBY 242424

DATE **Jan.31/00**

Printed in Great Britain

This document transmits Revision 1 to Service Bulletin EV2500-70-0718

Document History

Service Bulletin Revision Status
 Initial Issue May 27/99

Supplement Revision Status

Bulletin Revision 1

Remove
 Pages 1 to 4 of the
 Service Bulletin

Incorporate
 Pages 1 to 5 of the
 Service Bulletin

Reason for change
 To add two spacers to 2.
 Material Information and
 editorial changes

V2500-ENG-70-0718

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED-if any have not been received please advise
 Technical Publications Department, Rolls-Royce plc, Derby, England
 © Rolls-Royce plc (Date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin following incorporation of Revision 1 are as follows:

<u>Page</u>		<u>Revision Number</u>	<u>Revision Date</u>
	Bulletin		
R	1	1	Jan.31/00
R	2	1	Jan.31/00
R	3	1	Jan.31/00
R	4	1	Jan.31/00
R	5	1	Jan.31/00

Printed in Great Britain



International Aero Engines

SERVICE BULLETIN

INFORMATION - ENGINE - MAIN GEARBOX ASSEMBLY - INTRODUCTION OF REDESIGNED
TRANSPORTATION COVERS

Printed in Great Britain

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2530-A5
V2533-A5

BULLETIN INDEX LOCATOR

72-60-00

Compliance Category Code

7

Internal Reference No.

EC 97VF008

R May.27/99
R Jan.31/00

V2500-ENG-70-0718

© Rolls-Royce plc

Page 1 of 5



INFORMATION – ENGINE – MAIN GEARBOX ASSEMBLY – INTRODUCTION OF REDESIGNED
TRANSPORTATION COVERS

1. Planning Information

A. Effectivity

- (1) Aircraft: (a) Airbus A319.
(b) Airbus A320.
(c) Airbus A321.
- (2) Engines: (a) V2500-A1 Engines.
(b) V2522-A5 Engines.
(c) V2524-A5 Engines.
(d) V2527-A5 Engines.
(e) V2530-A5 Engines.
(f) V2533-A5 Engines.

B. Concurrent Requirements

None.

C. Reason

To announce a re-design of the transportation covers for the Hydraulic Pump and the Individual Drive Generators.

D. Compliance

For Information Only.

E. Approval

The part number transactions are given in the Material Information section of this Service Bulletin. They comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

F. References

- (1) IAE Engineering Change Number 97VF008

- R (2) IAE Engineering Change Number 97VF008A

G. General Information

Material Information section of this Service Bulletin gives the latest information about the availability of the affected parts.



H. Other Publications Affected

- (1) Illustrated Parts Catalogue (IPC), Chapter/Section 72-60-03.

Printed in Great Britain



2. Material Information

A. Kits necessary for this Service Bulletin

None.

Parts affected by this Service Bulletin.

72-60-03

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
	01060	4G0086	1	Cover, plain IDGS - drive	4P0140	(A)(B)(S1)
R	01065	4G0087	1	Spacer, IDGS and - HP covers	-	(A)
R	01090	4G0085	1	Cover, plain IDGS - drive	4P0139	(A)(B)(S1)
R	01095	4G0087	1	Cover, plain IDGS - drive	-	(A)

B. Instructions disposition codes:

- (1) (A) Part will be available from September 1999.
- (2) (B) Old parts will not be available
- (3) (S1) Old and new parts are fully interchangeable.



3. Accomplishment Instructions

None

Printed in Great Britain

