

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE: 860 565 5515
FAX: 860 565 0600

DATE: **May. 5/00**

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE - DERBY 242424

Printed in Great Britain

V2500-A1/A5/D5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin EV2500-70-0785

Bulletin Initial Issue

Remove

Incorporate
Pages 1 to 3 of the
Service Bulletin

Reason for change
Initial issue

V2500-ENG-70-0785
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

	May 5/00	
--	----------	--

2		
---	--	--

	May 5/00	
--	----------	--

3		
---	--	--

	May 5/00	
--	----------	--

Printed in Great Britain

V2500-ENG-70-0785

Transmittal - Page 2



GENERAL INFORMATION BULLETIN – TO ANNOUNCE THE AVAILABILITY OF REPAIR PARTS FOR THE
SCAVENGE OIL FILTER HOUSING ASSEMBLY

1. Planning Information

A. Effectivity

- (1) Airbus A319
V2522-A5, V2524-A5 Engines
- (2) Airbus A319CJ
V2527M-A5 Engines
- (3) Airbus A320
 - (a) V2500-A1 Engines
 - (b) V2527-A5, V2527E-A5 Engines
- (4) Airbus A321
V2530-A5, V2533-A5 Engines
- (5) Boeing – Long Beach Division MD-90
V2525-D5, V2528-D5 Engines
- (6) ATA Locator
79-22-43

B. Concurrent Requirements

None.

C. Reason

- (1) Problem
None.
- (2) Objective
To provide the availability of a repair part for the scavenge oil filter housing.



D. Compliance

For information only.

E. Approval

The part number changes and/or part modifications described in sections 2 and 3 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA APPROVED for the engine models listed.

F. Manpower

Not applicable.

G. References

- (1) IAE Engineering Change Number 99VF013.
- (2) The Material Information section of this Service Bulletin provides the latest information concerning the availability of the insert for the oil scavenge filter casing.

H. Other Publications Affected

- (1) The Illustrated Parts Catalogue (IPC), Chapter/Section 79-22-43, Fig 01 will be revised to show the part introduced by this Service Bulletin.
- (2) The Component Maintenance Manual, Chapter/Section 79-22-43, will be revised to incorporate Repair VRS5656.



2. Material Information

A. Applicability : For each model to incorporate this Service Bulletin.

B. Parts affected by this Service Bulletin:

79-22-43

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	OLD PART NO.	INSTR DISP
01571	KU37022	15	Insert	-	(A)

C. Instructions disposition codes:

(A) Part is available for sale.

3. Accomplish Instructions

None.

