



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - TRANSFER VARIOUS BRACKETS TO MORE APPROPRIATE CHAPTERS

MODEL APPLICATION

V2500-A1
V2522-A5
V2524-A5
V2527-A5
V2527E-A5
V2527M-A5
V2530-A5
V2533-A5

BULLETIN INDEX LOCATOR

72-50-00
73-11-00

Compliance Category Code

8

Internal Reference No.

00VK010

Sep.29/00

V2500-ENG-70-0797

Page 1 of 3



International Aero Engines INFORMATION BULLETIN

INFORMATION - ENGINE - TRANSFER VARIOUS BRACKETS TO MORE APPROPRIATE CHAPTERS

1. Planning Information

A. Effectivity

- (1) Aircraft: Airbus A319, A320, A321
- (2) Engine: V2500-A1/A5

B. Reason

Transfer various brackets to chapters containing the clipping hardware and tubes associated with the brackets. The more appropriate locations will eliminate possible customer confusion.

This is a configuration control tracking system adjustment only and does not affect engine hardware.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.


D. Approval

The Part Number transactions shown under the Material Information portion of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

- (1) IAE Engineering Change 00VK010.
- (2) V2500-A1 Engine Illustrated Parts Catalog (S-V2500-1IA) to relocate the bracket.
- (3) V2500-A5 Engine Illustrated Parts Catalog (S-V2500-2IA, S-V2500-2IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB,) to relocate the bracket.

Printed in Great Britain



International Aero Engines INFORMATION BULLETIN

F. General Information

The Material Information portion of this Bulletin provides the latest information concerning the location of the Brackets.. The Bracket locations were transferred to eliminate possible customer confusion.

G. Material Information

New Part No. (ATA No.)	Qty	Est'd Unit Price(\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
------------------------------	-----	----------------------------	---------	------------------------------	-----------------------------

Applicability: For each V2500-A1/A5 Engine to incorporate this Service Bulletin

(72-50-53)	1		Bracket, Loop Clamp	2A3119 (20-085)	(1)
2A3119 (73-22-51)	1		Bracket, Loop Clamp	(20-085)	(1)
(72-50-53)	1		Bracket, Loop Clamp	2A3119 (20-217)	(1)
2A3119 (73-22-51)	1		Bracket, Loop Clamp	(20-217)	(1)
(72-50-53)	1		Bracket, Loop Clamp	2A3120 (20-020)	(1)
2A3120 (73-22-51)	1		Bracket, Loop Clamp	(20-020)	(1)
(72-50-53)	1		Bracket, Loop Clamp	2A3123 (20-355)	(1)
2A3123 (73-22-51)	1		Bracket, Loop Clamp	(20-355)	(1)
(73-11-41)	1		Bracket, Loop Clamp	2A3277 (01-355)	(1)
2A3277 (72-40-00)	1		Bracket, Loop Clamp	(01-270)	(1)

H. Instructions/Disposition Code Statements:

(1) Brackets transferred to a more appropriate chapter.

NOTE: The estimated unit prices, if shown, are provided for planning purposes only and do not constitute a firm quotation. Consult the IAE Price Catalog or contact yams Spare Parts Sales Department for information concerning firm prices.