

**International Aero Engines****RR-DERBY**

400 MAIN STREET, MAIL STOP 121-10  
EAST HARTFORD, CT 06108, USA.  
TELEPHONE: 860 565 5515  
FAX: 860 565 0600

P.O. BOX 31, DERBY  
TELEGRAMS - 'ROYCAR' DERBY  
TELEX - 37645  
TELEPHONE - DERBY 242424

DATE: **Sep.20/02****V2500 A5 INFORMATION SERVICE BULLETIN**

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0818

Bulletin Initial Issue

Remove

Incorporate  
Page 1 and 2 of the  
Service Bulletin

Reason for change  
Initial issue

**V2500-ENG-70-0818**  
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED  
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England  
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Sep.20/02
--	--	-----------

2		
---	--	--

		Sep.20/02
--	--	-----------

Printed in Great Britain

V2500-ENG-70-0818  
Transmittal - Page 2



INFORMATION – ENGINE – LP TURBINE – TO USE PRE V10198 ENGINE PARTS IN A5 33K ENGINES

1. Planning Information

A. Effectivity

(1) Aircraft: Airbus A319 / A320 / A321

(a) V2533-A5 Engines

(2) ATA Location: 72-24-49

B. Reason

To allow the use of pre V10198 ACC Connectors, A/O-Tube, Seal, Ring Periseal and Support Assemblies for the 33k model. The parts were originally introduced into the A1 engine model and later carried over to the A5 baseline standard. The upgrade to 33k configuration has no effect on these parts, which are externals. Existing 33k hardware superseding these parts were introduced for reason of cost and manufacturing only. Structural integrity and function is not affected.

C. Compliance

Category Code 8

Accomplish based upon experience with the prior configuration.

D. Approval

The part number transactions shown under sub-paragraph of the MATERIAL INFORMATION paragraph have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for Engine Models Listed.

E. General Information

The Material Information portion of this Bulletin provides the latest information concerning the availability of the affected parts.

F. References

(1) Internal Reference No. EC33CN003



## 2. Material Information

A. \_

75-24-49

Fig- Item	New Part Number	Qty	Est'd (\$) Unit Price	Keyword	Old Part Number	Qty	Supply status
01-010	3A1549	1	N/A	Connector,	N/A	-	-
01-640	3A0189	2	N/A	A/O Tube Seal,	N/A	-	-
01-740	3A0189	2	N/A	Ring Periseal Seal,	N/A	-	-
02-490	3A1749	1	N/A	Ring Periseal Support,	N/A	-	-
02-720	3A1752	1	N/A	Assy (No.2)	N/A	-	-
03-490	3A1762	1	N/A	Support, Assy (No.6)	N/A	-	-
03-490	3A2320	1	N/A	Support, Assy (No.6)	N/A	-	-
03-720	3A1759	1	N/A	Support, Assy (No.5)	N/A	-	-
04-010	3A1745	1	N/A	Support, Assy (No.1)	N/A	-	-
04-010	3A1755	1	N/A	Support, Assy (No.4)	N/A	-	-

Printed in Great Britain

## 3. Accomplishment Instructions

None.