



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Jun.30/05

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500 D5 SERIES PROPULSION SYSTEM SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0897

Bulletin Initial Issue

Remove

Incorporate
Page 1 and 2 of the
Service Bulletin

Reason for change
Initial issue

V2500-ENG-70-0897

Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Publication Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		
---	--	--

		Jun.30/05
--	--	-----------

2		
---	--	--

		Jun.30/05
--	--	-----------

Printed in Great Britain

V2500-ENG-70-0897
Transmittal - Page 2

INFORMATION – ANNOUNCEMENT OF CORRECT VENDOR PART NUMBER FOR THE EGT HARNESS JUNCTION
BOX COVER – MOD 70-0897

1. Planning Information

A. Effectivity

(1) Boeing – Longbeach Division MD-90

(a) V2525-D5, V2528-D5 Engines prior to Serial No. V20286.

B. Reason

To announce the change to a Vendor Part Number for the EGT Harness Junction Box Cover.

C. Compliance

For information only.

D. Approval

The part number transactions shown under Section 2 Material Information of this Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. References

(1) IAE Engineering Change Number – 05VI002.

(2) ATA Locator – 77-21-43.

F. Other Publications Affected

(1) Illustrated Parts Catalogue will be revised.

G. General Information

The Material Information section of this Bulletin provides the latest information concerning the availability of the affected parts.

2. Material Information

A. New Parts:

Applicability: For each V2500 engine to incorporate this Bulletin.

77-21-43

FIG ITEM NUMBER	NEW PART NUMBER	QTY	PART TITLE	MAT	OLD PART NUMBER	INSTR/ DISPOS (S1)
02070	HDC18666	1	..Cover (V00060)	-	HDB18666	

B. Instruction Dispositions Codes:

(S1) Old and new parts are freely and fully interchangeable.

3. Accomplishment Instructions

A. None