



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: May.26/08

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Revision 1 to Service Bulletin V2500-ENG-70-0902

Document History

Service Bulletin Revision Status

Initial Issue May.14/08

Service Bulletin Revision 1

Remove	Incorporate	Reason for change
All pages of the Service Bulletin	Pages 1 to 4 of the Service Bulletin.	To revise Instruction/Disposition Codes.

V2500-ENG-70-0902

Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED

If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England

© Rolls-Royce plc (date as above) Printed in Great Britain

INFORMATION – ENGINE – TO ANNOUNCE THE AVAILABILITY OF NEW 4W2001, 4W2002 AND 4W2003
SERIES WASHERS AS REPLACEMENTS FOR THE AN960 SERIES WASHERS THAT ARE NO LONGER
AVAILABLE

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Engines.
- (2) Airbus A320
 - (a) V2500-A1 Engines.
 - (b) V2524-A5, V2527-A5, V2527E-A5 Engines.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Engines.

B. Reason

To announce the availability of new 4W2001, 4W2002 and 4W2003 series washers as replacements for the AN960 series washers that are no longer available.

C. Compliance

Category Code 7.

Accomplish when supply of superseded parts has been depleted.

D. Approval

The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

The authorising IAE document is EC 06VN300.

E. References

- (1) IAE Engineering Change No. 06VN300.
- (2) NAS1149 Specification.
- (3) ATA Locators, 73-11-47.

F. General Information

- (1) This General Information Bulletin introduces new 4W2001, 4W2002 and 4W2003 series washers as replacements for the AN960 series washers.
- (2) Publications affected:
 - (a) The V2500-A1/A5 Engine Illustrated Parts Catalogs will be revised to include the new washers. See "Material Information" section for ATA Locations.

2. Material Information

A. Part Prices:

Not applicable.

B. Parts affected by this Service Bulletin:

Applicability: For all V2500-A1/A5 Engines.

The following parts are affected in the V2500-A1/A5 Engine Illustrated Parts Catalogs:

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT OLD PART NO.	INSTR DISP
73-11-47					
01108	4W2001	A/R	.Washer	- AN960C2616	(A)(B)(S1)
02112	4W2002	1	.Washer	- AN960C1216	(A)(B)(S1)
02113	4W2003	1	.Washer	- -	(A)

C. Instruction/Disposition Codes:

(A) New parts are available.

R (B) The old part will no longer be available when stock of the old part is exhausted.

R (S1) The old part number may be used as a replacement only where the old part number was installed. The new part is an acceptable replacement for the old or new part number.

3. Accomplishment Instructions

None.