



400 MAIN STREET, MAIL STOP 121-10
EAST HARTFORD, CT 06108, USA.
TELEPHONE:- 860 565 5515
FAX:- 860 565 0600

DATE: Aug. 9/07

P.O. BOX 31, DERBY
TELEGRAMS - 'ROYCAR' DERBY
TELEX - 37645
TELEPHONE:- 44 (0) 1332 242424
FAX:- 44 (0) 1332 249936

V2500-A1/A5 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

Printed in Great Britain

This document transmits the Initial Issue of Service Bulletin EV2500-70-0904

Bulletin Initial Issue

Remove	Incorporate Pages 1 to 4 of the Service Bulletin	Reason for change Initial Issue.
--------	--	-------------------------------------

V2500-ENG-70-0904
Transmittal - Page 1 of 2

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain

LIST OF EFFECTIVE PAGES

The effective pages to this Service Bulletin are as follows:

<u>Page</u>	<u>Revision Number</u>	<u>Revision Date</u>
-------------	------------------------	----------------------

Bulletin		
----------	--	--

1		Aug.9/07
2		Aug.9/07
3		Aug.9/07
4		Aug.9/07

Printed in Great Britain

V2500-ENG-70-0904
Transmittal - Page 2

INFORMATION – NACELLE – TO ANNOUNCE THE AVAILABILITY OF TWO MODIFIED STAINLESS STEEL
TAB WASHERS ON THE HYDRAULIC SYSTEM

1. Planning Information

A. Effectivity

- (1) Airbus A319
 - (a) V2522-A5, V2524-A5, V2527M-A5 Nacelles.
- (2) Airbus A320
 - (a) V2500-A1 Nacelles.
 - (b) V2527-A5, V2527E-A5 Nacelles.
- (3) Airbus A321
 - (a) V2530-A5, V2533-A5 Nacelles.

B. Reason

- (1) To announce the availability of two modified stainless steel tab washers on the hydraulic system. The modified washers have the requirement for zinc coating removed.

C. Compliance

- (1) Category Code 7.

Accomplish when supply of superseded parts has been depleted.

D. Approval

- (1) The technical content of this Service Bulletin has been approved under the authority of the EASA Design Organisation Approval No EASA.21J.031.

E. General Information

- (1) This General Information Bulletin introduces a modified zinc free tab washer used in two places on the hydraulic system. The stainless steel tab washers are now manufactured without the need for zinc spray operation.



(2) Publications affected

- (a) The V2500-A1/A5 Engine Illustrated Parts Catalogs (S-V2500-1IA, S-V2500-2IA, S-V2500-2IB, S-V2500-5IA, S-V2500-5IB, S-V2500-6IA, S-V2500-6IB, S-V2500-7IA, S-V2500-7IB) will be revised to include the modified stainless steel tab washers on the hydraulic system. Refer to Section 2. "Material Information" for ATA Locations.

F. References

(1) Internal Reference No.:

Engineering Change No. 05VN317 issue 1.

(2) Shorts Modification No. D1184.

(3) ATA Locator - 29-11-17.

2. Material Information

A. Part Prices:

Not applicable.

B. Parts affected by this Service Bulletin:

Applicability: For all V2500- A1/A5 Nacelles

FIG ITEM NO.	NEW PART NO.	QTY	PART TITLE	MAT	OLD PART NO.	INSTR DISP
29-11-17						
01-027	745-5022 -503	2	.WASHER, TAB	-	745-5022 -501	(A)(B) (S1)

C. Instruction/Disposition Codes:

(A) New parts are available.

(B) The old part will no longer be available when stock of the old part is exhausted.

(S1) The old part number may be used as a replacement only where the old part number was installed. The new part is an acceptable replacement for the old or new part number.

3. Accomplishment Instructions.

None.