400 MAIN STREET, MAIL STOP 121-10 EAST HARTFORD, CT 06108, USA. TELEPHONE:- 860 565 5515 FAX:- 860 565 0600

Printed in Great Britain

P.O. BOX 31, DERBY TELEGRAMS - 'ROYCAR' DERBY TELEX - 37645 TELEPHONE:- 44 (0) 1332 242424 FAX:- 44 (0) 1332 249936

DATE: Nov. 12/08

V2500-A1 SERIES PROPULSION SYSTEMS SERVICE BULLETIN

This document transmits the Initial Issue of Service Bulletin V2500-ENG-70-0981

Service Bulletin Initial Issue

Remove Incorporate Reason for change

Pages 1 to 3 of the Service Bulletin

Initial Issue.

V2500-ENG-70-0981
Transmittal - Page 1 of 1

CHECK THAT ALL PREVIOUS TRANSMITTALS HAVE BEEN INCORPORATED
If any have not been received please advise Customer Data Services, Rolls-Royce plc, Derby, England
© Rolls-Royce plc (date as above) Printed in Great Britain





#### SERVICE BULLETIN

# INFORMATION - ENGINE - LP COMPRESSOR - TO ANNOUNCE THE AVAILABILITY OF THE NEW WASHER

### 1. Planning Information

### A. Effectivity

- (1) Airbus A320
  - (a) V2500-A1.

#### B. Reason

To announce the availability of the new washer.

#### C. Compliance

Category Code 7.

Accomplish when supply of superseded parts has been depleted.

#### D. Approval

The part number changes and/or part modifications described in section 2 of this Service Bulletin have been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the engine models listed.

# E. General Information

(1) The Material Information portion of this Service Bulletin provides the latest information concerning the availability of the new washer.

#### F. References

(1) Internal Reference No.:

Engineering Change No. 08VJ005.

- (2) IAE V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-00 Figure 02.
- (3) ATA Locator -72-32-00.

# G. Other Publications Affected

(1) IAE V2500 Engine Illustrated Parts Catalog, Chapter/Section 72-32-00 Figure 02 will be revised.

Nov.12/08 Nov.12/08 Initial Issue V2500-ENG-70-0981



#### **SERVICE BULLETIN**

# 2. <u>Material Information</u>

# A. Parts affected by this Service Bulletin

Applicability: For V2500-A1 Engines

FIG	NEW	QTY	PART TITLE	MAT	OLD	INSTR
ITEM	PART				PART	DISP
NO.	NO.				NO.	

72-32-00

02-855 MS51496 10 .Washer - MS51496 (A)(B)(S1) P75 C75

# B. <u>Instruction/Disposition Codes:</u>

- (A) New part will be available when existing stock of old parts has been depleted.
- (B) Old parts will continue to be supplied until existing supplies have been depleted.
- (S1) Old and new parts are freely and fully interchangeable, both physically and functionally.

Nov.12/08 Nov.12/08 Initial Issue

# SERVICE BULLETIN

3. Accomplishment Instructions

None.

Printed in Great Britain

Nov.12/08 Nov.12/08 Initial Issue V2500-ENG-70-0981