



SERVICE BULLETIN

ENGINE - MAIN GEARBOX ASSEMBLY - PROVIDE A NEW IDG MOUNTING PAD FEATURING AN ADDED DOWEL PIN HOLE - CATEGORY CODE 7 - MOD.ENG-72-0086

1. Planning InformationA. Effectivity

- (1) Aircraft: Airbus A320
- (2) Engine: V2500-A1 Engines before Serial No.V0086

B. Reason

To provide a new IDG housing with an added dowel pin hole to allow the installation of the redesigned QAD.

C. Compliance

Category Code 7

Accomplish when the supply of the superseded parts have been depleted.

Approval

The Part Number transaction shown under Material Information portion of this Bulletin has been shown to comply with the applicable Federal Aviation Regulations and are FAA-APPROVED for the Engine Model listed.

E. Reference

- (1) Internal Reference No.

EC88VF079

F. General Information

The Material Information portion of this Bulletin provides the latest information concerning the availability of the gearbox module, main gearbox assembly and IDG housing A/O.

V2500-ENG-72-0086

May.24/91

Page 1 of 2



SERVICE BULLETIN

3. Material Information

Applicability: For each V2500 Engine to incorporate this Bulletin.

A. Kits associated with this Bulletin:

None

B. Parts affected by this Bulletin:

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Instructions Disposition
4A1050 (72-60-00)	1	-	GBX Module	4A0504 (01-001)	(A)(B)(S1) (S2)
4A1100 (72-60-10)	1	-	Gearbox, Assy Main	4A0053 (01-001)	(A)(B)(S1) (S2)
4B0281 (72-60-28)	1	1989.00	.Housing A/O IDG	4B0271 (01-450)	(A)(B)(S1) (S2)

C. Instruction/Disposition Code Statements:

- (A) New part is currently available.
- (B) Old part will be no longer available.
- (S1) New part coded (S1) is interchangeable with old part.
- (S2) Old part coded (S2) is not interchangeable with new part.

NOTE: Contact IAE's Spare Parts Sales Department for information concerning firm prices.

V2500-ENG-72-0086