

International Aero Engines
INFORMATION BULLETIN

Jan. 29/99

Subject: Transmittal of Revision 1 to Non-Modification Service Bulletin V2500-ENG-72-0322.

Service Bulletin Revision History:

Initial Issue	July 15/98.
Revision 1	Jan. 29/99.

Reason for Revision :

(1) To cancel the Initial Issue of Non-Modification Service Bulletin ENG 72-0322.

Effect On Past Compliance:


None.

List of Effective Pages:

<u>Page No.</u>	<u>Revision No.</u>	<u>Effective Page</u>
1 to 4	Revision 1	Jan. 29/99.

V2500-ENG-72-0322

Transmittal
Page 1 of 1



International Aero Engines
INFORMATION BULLETIN

ENGINE - LUBRICATION PROCEDURE FOR HPC VSV MECHANISM (NON-MODIFICATION)

MODEL APPLICATION

V2500-A1
V2500-A5

BULLETIN INDEX LOCATOR


72-41-00

Compliance Category Code

R 3

Internal Reference No.

EC98VR789A EC98VR789B



International Aero Engines
INFORMATION BULLETIN

ENGINE - LUBRICATION PROCEDURE FOR HPC VSV MECHANISM (NON-MODIFICATION)

1. Planning Information

A. Effectivity

(1) Aircraft:

- (a) Airbus A319.
- (b) Airbus A320.
- (c) Airbus A321.

(2) Engines:

- (a) V2500-A1 All engines.
- (b) V2500-A1 All engines.

R B. Reason


- (1) The purpose of this issue of Non-Modification Service Bulletin ENG-72-0322 is to cancel the instructions contained in the Initial Issue.
- (2) The content of this Non-Modification Service Bulletin will be included as a TASK in the A319/A320/A321 Aircraft Maintenance Manual (AMM).



International Aero Engines
INFORMATION BULLETIN

R 2. Material Information

Not applicable.



International Aero Engines
INFORMATION BULLETIN

R 3. Accomplishment Instructions

Not applicable.