



STANDARD PRACTICES - ENGINE - INFORMATION - ANNOUNCEMENT OF NEW FIRE DETECTION SYSTEM
"B" HARNESS EBU CORE SERVICES HARNESS, INTERPHONE JACK CABLE AND P2/T2 CABLE ASSEMBLIES
- CATEGORY CODE 7 - MOD.NAC-70-0098

1. Planning Information

A. EFFECTIVITY

(1) AIRCRAFT: Airbus A320

(2) NACELLE: V2500-A1

B. REASON

To announce the availability of new EBU fire detection system "B" harness, core services harness, interphone jack cable, and P2/T2 cable assemblies.

C. COMPLIANCE

Category Code 7

Accomplish when the supply of superseded parts has been depleted.

D. APPROVAL

The part number changes shown in paragraph G of this service bulletin have been sanctioned under a product development control system that has been approved by the DGAC (Direction Generale de l'Aviation Civile -France).

E. REFERENCES

(1) Internal Reference No.

88VN147A & 89VN122/A

F. GENERAL INFORMATION


(1) Part numbers changed due to backshells being changed to a non decoupling type

(2) The Material Information portion of this bulletin provides the latest information concerning the availability of the new harnesses.

(3) Other publications affected

(a) The V2500 Engine Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA locations.

V2500-NAC-70-0098



International Aero Engines
INFORMATION BULLETIN

(b) The V2500 Power Plant Illustrated Parts Catalog will be revised to include the new parts. See "Material Information" section for ATA locations.

(c) The V2500 Component Maintenance Manual will be included the new parts. See "Material Information" section for ATA locations.

G. MATERIAL INFORMATION

Applicability: For each V2500 Nacelle to incorporate this bulletin.

New Part No. (ATA No.)	Qty	Est'd Unit Price (\$)	Keyword	Old Part No. (IPC No.)	Supply Status
387AS008M1404A2 (23-44-41)	1	\$ 360.00	Backshell	380AS003M1404A2 (01-100)	(A)(B)
740-3000-589 (71-11-11)	1	RQ*	Inlet Cowl	740-3000-585 (01-005)	(A)(B)(1)
740-3234-507 (71-11-43)	1	\$3,687.00	Cable Assy P2/T2	740-3234-505 (01-100)	(C)(1)
740-3235-507 (71-11-43)	1	RQ*	Cable Assy (P2/T2)	740-3235-505 (01-500)	(C)(1)
740-5862-505 (71-52-42)	1	\$4,163.00	Harness	740-5862-503 (01-005)	(A)
387AS008M1203A2 (71-11-43) (71-11-43)	2	\$ 241.00	Backshell	380AS003M1203A2 (01-535) (01-170)	(A)
387AS008M1606A3 (71-11-43)	1	\$ 241.00	Backshell	380AS003M1606A3 (01-570)	(A)
387AS008M1204A2 (71-52-41) (71-52-41)	4	\$ 241.00	Backshell	380AS003M1204A2 (02-015) (02-050)	(A)
387AS008M1406A2 (71-52-41)	1	\$ 241.00	Backshell	380AS003M1406A2 (02-085)	(A)
387AJ008M1004A (71-52-41)	1	\$ 360.00	Backshell	380AA003M1004A (02-210)	(A)
387AS008M1006A2 (71-52-41)	1	\$ 241.00	Backshell	380AS003M1006A2 (02-240)	(A)
387AS008M1206A2 (71-52-41)	1	\$ 369.00	Backshell	380AS003M1206A2 (02-275)	(A)


RQ* = Quote only basis.

(A) New parts are currently available.

(B) The Old parts will no longer be available for sale when the old part is exhausted.

Printed in Great Britain

V2500-NAC-70-0098



International Aero Engines

INFORMATION BULLETIN

(C) Not available as a spare for replenishment.

(1) Old part number may be used as a replacement only where old part number was installed. New part number is acceptable replacement for the old or new part number.

NOTE The estimated 1992 Unit Price shown is provided for planning purposes only and does not constitute a firm quotation. Consult the Rohr Price Catalog or contact Rohr's Spare Parts Sales Department for information concerning firm price.

Printed in Great Britain

V2500-NAC-70-0098

May.31/93

Page 3

